Huron High School						
Location	Parameter	Result	MCL/AL	Method Reference		
Huron-14: Pool, East, Near Diving Boards, Glass Filler on Bubbler	E. coli	Negative	Zero	ATP D05-0035		
Huron-32: Kitchen, Single Sink, Faucet Huron-33: Room 6152, Staff Lounge, Single Sink, Faucet	Total Coliforms <i>E. coli</i>	Negative Negative	Zero Zero	ATP D05-0035 ATP D05-0035		
	Total Coliforms	Negative	Zero	ATP D05-0035		
	E. coli  Total Coliforms	Negative Negative	Zero Zero	ATP D05-0035 ATP D05-0035		
Huron-40: Room Between Room 2201 and Room 2200, 2- Compartment Sink, "Green House", Kitchen Fauccet	E. coli  Total Coliforms	Negative  Negative	Zero	ATP D05-0035		
Huron-52: Room 6216, 2- Compartment Sink, Faucet	E. coli  Total Coliforms	Negative  Negative	Zero	ATP D05-0035		
Huron-66: Hallway, Floor 3, Outside Room 4311, Hydration Station, Bottle Fill	E. coli  Total Coliforms  Total Residual Chlorine	Negative Negative 0.0 PPM	Zero Zero N/A	ATP D05-0035  ATP D05-0035  N/A		
Huron-84: Hallway, Southeast Wing, Floor 1, Outside of Media Center, Right Hydration Station, Bottle Fill	E. coli  Total Coliforms	Negative Negative	Zero	ATP D05-0035  ATP D05-0035		
Huron-92: Outbuilding, Football Field, Locker Room Clinic, Single Sink	E. coli  Total Coliforms	Negative Negative	Zero	ATP D05-0035		
Huron-95: Outbuilding, Football Field, Concessions, 3- Compartment Add On, Single Cold Water Faucet, Far Right	E. coli	Negative	Zero	ATP D05-0035		
Faucet	Total Coliforms	Negative	Zero	ATP D05-0035		

Sampling Date: October 22, 2020

Sampler: Jackie Keeler

## Huron High School Sampling Results Table

Huron High School						
Location	Parameter	Result	MCL/AL	Method Reference		
Huron-102: Hallway, Southeast Wing, Floor 2, Across from	E. coli	Negative	Zero	ATP D05-0035		
Room 5200, Hydration Station, Bottle Fill	Total Coliforms	Negative	Zero	ATP D05-0035		

Sampling Date: October 22, 2020

Sampler: Jackie Keeler