



Ann Arbor Public Schools  
 Drinking Water Analysis  
 Project Number: AE230030

| Thurston Elementary School        |   |                   |                |  |                     |                     |                        |                   |                               |
|-----------------------------------|---|-------------------|----------------|--|---------------------|---------------------|------------------------|-------------------|-------------------------------|
| Date of Sampling: January 3, 2023 |   |                   |                |  |                     |                     |                        |                   |                               |
| Sampler: Sabrina Fouche           |   |                   |                |  |                     |                     |                        |                   |                               |
| Sample #                          | Location                                | Type <sup>1</sup> | Time Collected | District Lead Action Level (ug/L) <sup>2</sup> | Lead Results (ug/L) | Aerator Present Y/N | POU Filter Present Y/N | Filter Date/Color | Notes                         |
| Thurston-07                       | Room C2, Combination Sink, Glass Filler | C                 | 11:22 AM       | 5  | ND <sup>3</sup>     | N                   | Y                      | 6/24/22           | Initial First Draw, Filtered. |
| Thurston-11                       | Room 9, Combination Sink, Glass Filler  | C                 | 11:00 AM       | 5  | ND                  | N                   | Y                      | Unknown           | Initial First Draw, Filtered. |
| Thurston-15                       | Room 26, Combination Sink, Glass Filler | C                 | 10:52 AM       | 5  | ND                  | N                   | Y                      | 6/28/22           | Initial First Draw, Filtered. |
| Thurston-21                       | Room 27, Combination Sink, Glass Filler | C                 | 10:55 AM       | 5  | ND                  | N                   | Y                      | 6/28/22           | Initial First Draw, Filtered. |
| Thurston-23                       | Room 25, Combination Sink, Glass Filler | C                 | 10:49 AM       | 5  | ND                  | N                   | Y                      | 6/28/22           | Initial First Draw, Filtered. |

1) Type: B = Bubbler, HS = Hydration Station, BT = Single Bottle Fill, WC = Single Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, PB = Potable Bathroom Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee Machine, G = Glass Filler

2) [https://www.epa.gov/sites/default/files/2016-06/documents/npwdr\\_complete\\_table.pdf](https://www.epa.gov/sites/default/files/2016-06/documents/npwdr_complete_table.pdf)

3) ND = Non-Detected at Reported Detection Limit of 1 ug/L



Ann Arbor Public Schools  
 Drinking Water Analysis  
 Project Number: AE230030

| Thurston Elementary School        |   |                   |                |  |                     |                     |                        |                   |                               |
|-----------------------------------|---|-------------------|----------------|--|---------------------|---------------------|------------------------|-------------------|-------------------------------|
| Date of Sampling: January 3, 2023 |   |                   |                |  |                     |                     |                        |                   |                               |
| Sampler: Sabrina Fouche           |   |                   |                |  |                     |                     |                        |                   |                               |
| Sample #                          | Location  | Type <sup>1</sup> | Time Collected | District Lead Action Level (ug/L) <sup>2</sup> | Lead Results (ug/L) | Aerator Present Y/N | POU Filter Present Y/N | Filter Date/Color | Notes                         |
| Thurston-33                       | Room K11, Combination Sink, Glass Filler                                | C                 | 11:07 AM       | 5  | ND                  | N                   | Y                      | 6/24/22           | Initial First Draw, Filtered. |
| Thurston-39                       | Room K12, Combination Sink, Glass Filler                                | C                 | 11:14 AM       | 5  | ND                  | N                   | Y                      | 6/24/22           | Initial First Draw, Filtered. |
| Thurston-49                       | Room 5, Combination Sink, Glass Filler                                  | C                 | 11:26 AM       | 5  | ND                  | N                   | Y                      | 6/24/22           | Initial First Draw, Filtered. |
| Thurston-54                       | Hallway, Left of Multipurpose Room D103, Hydration Station, Bottle Fill | HS                | 11:30 AM       | 5  | ND                  | Y                   | Y                      | Flashing Red      | Initial First Draw, Filtered. |
| Thurston-12                       | Room 10, Combination Sink, Glass Filler                                 | C                 | 11:43 AM       | 5  | ND                  | N                   | Y                      | 6/27/22           | Initial First Draw, Filtered. |

1) Type: B = Bubbler, HS = Hydration Station, BT = Single Bottle Fill, WC = Single Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, PB = Potable Bathroom Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee Machine, G = Glass Filler

2) [https://www.epa.gov/sites/default/files/2016-06/documents/npwdr\\_complete\\_table.pdf](https://www.epa.gov/sites/default/files/2016-06/documents/npwdr_complete_table.pdf)

3) ND = Non-Detected at Reported Detection Limit of 1 ug/L



Ann Arbor Public Schools  
 Drinking Water Analysis  
 Project Number: AE230030

| Thurston Elementary School        |  |                   |                |  |                     |                     |                        |                   |                               |
|-----------------------------------|--|-------------------|----------------|--|---------------------|---------------------|------------------------|-------------------|-------------------------------|
| Date of Sampling: January 3, 2023 |  |                   |                |  |                     |                     |                        |                   |                               |
| Sampler: Sabrina Fouche           |  |                   |                |  |                     |                     |                        |                   |                               |
| Sample #                          | Location   | Type <sup>1</sup> | Time Collected | District Lead Action Level (ug/L) <sup>2</sup> | Lead Results (ug/L) | Aerator Present Y/N | POU Filter Present Y/N | Filter Date/Color | Notes                         |
| Thurston-63                       | Hallway, Outside Room 22, Hydration Station, Bottle Fill | HS                | 10:45 AM       | 5  | ND                  | Y                   | Y                      | Green             | Initial First Draw, Filtered. |

1) Type: B = Bubbler, HS = Hydration Station, BT = Single Bottle Fill, WC = Single Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, PB = Potable Bathroom Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee Machine, G = Glass Filler

2) [https://www.epa.gov/sites/default/files/2016-06/documents/npwdr\\_complete\\_table.pdf](https://www.epa.gov/sites/default/files/2016-06/documents/npwdr_complete_table.pdf)

3) ND = Non-Detected at Reported Detection Limit of 1 ug/L