



**Ann Arbor Public Schools  
Drinking Water Analysis  
Project Number: AE240030**

<b>Site: Carpenter Elementary School</b>									
<b>Sampling Type: Initial First Draw Sampling (IFD)</b>									
<b>Date of Sampling: February 16, 2024</b>									
<b>Sampler: Stephanie Waranauckas</b>									
Sample #	Location	Fixture Type	Time Collected	District Lead Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	POU Filter Present Y/N	Filter Date	Notes
Carpenter-04	Room C-140, Combination Sink, Glass Filler	Combination Sink	4:00 PM	5	ND	Y	Y	7/14/2023	
Carpenter-12	Room C-123, Combination Sink, Glass Filler	Combination Sink	3:25 PM	5	ND	Y	Y	7/14/2023	
Carpenter-18	Room C-116, Combination Sink, Glass Filler	Combination Sink	3:40 PM	5	ND	Y	Y	7/14/2023	
Carpenter-29	Room C-119, Combination Sink, Glass Filler	Combination Sink	3:35 PM	5	ND	Y	Y	7/14/2023	
Carpenter-33	Hallway, Outside Room C-125, Hydration Station, Bottle Fill	Hydration Station	4:05 PM	5	ND	Y	N	N/A	
Carpenter-37	Room C-138, Combination Sink, Glass Filler	Combination Sink	3:50 PM	5	ND	Y	Y	7/14/2023	
Carpenter-43	Room C-139, Combination Sink, Glass Filler	Combination Sink	3:55 PM	5	ND	Y	Y	7/14/2023	
Carpenter-52	Cafeteria, Hydration Station, Bottle Fill	Hydration Station	3:15 PM	5	ND	Y	N	N/A	
Carpenter-54	Hallway, Right of A/V Room 300, Hydration Station, Bottle Fill	Hydration Station	3:45 PM	5	ND	Y	N	N/A	

\*ND = Non-Detected at Reported Detection Limit of 1 ug/L