



**Ann Arbor Public Schools  
Drinking Water Analysis  
Project Number: AE240030**

Site: Clague Middle School									
Sampling Type: Initial First Draw Sampling (IFD)									
Date of Sampling: January 20, 2024									
Sampler: Dean Johnson									
Sample #	Location	Fixture Type	Time Collected	District Lead Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	POU Filter Present Y/N	Filter Date	Notes
Clague-40	Pool, South Wall, Southeast Corner, Stainless, Glass Filler	Single Bottle Fill	12:37pm	5	ND	Y	N	N/A	
Clague-05	Pool, South Wall, Southwest Corner, Left Bottle Fill	Single Bottle Fill	12:40pm	5	ND	Y	N	N/A	
Clague-10	Room 226, Combination Sink, Glass Filler	Combination Sink	1:29pm	5	ND	Y	Y	N/A	
Clague-13	Hallway, Outside Room 229 and Elevator, Hydration Station, Bubbler	Hydration Station	1:20pm	5	ND	Y	N	N/A	
Clague-16	Hallway, Outside Room 216, Hydration Station, Bottle Fill	Hydration Station	1:15pm	5	ND	Y	N	N/A	
Clague-19	Room 228, Combination Sink, Glass Filler	Combination Sink	1:25pm	5	ND	Y	Y	N/A	
Clague-26	Room 208, Combination Sink, Glass Filler	Combination Sink	1:10pm	5	ND	Y	Y	N/A	
Clague-29	Gym, South Corner, Porcelain, Glass Filler	Single Bottle Fill	1:04pm	5	ND	Y	N	N/A	
Clague-38	Hallway, Outside Room 144, Refridgerated, Glass Filler	Water Cooler	12:30pm	5	ND	Y	N	N/A	
Clague-41	Hallway, Outside Room 131, Hydration Station, Bottle Fill	Hydration Station	12:45pm	5	1	Y	N	N/A	
Clague-46	Media Center Work Room, Faucet	Faucet	12:55pm	5	3	Y	N	N/A	

\*ND = Non-Detected at Reported Detection Limit of 1 ug/L