



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Ann Arbor Open School @ Mack							
Date of Sampling: 11/3/2018							
Sampler: Alec Staber							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
A2SOM-01	Hallway, Right of Room 209, Bubblers	C	9:46 AM	5	ND ³	N	First Draw. Corrosion.
A2SOM-02	Room 205, Water Cooler	WC	9:48 AM	5	ND	N	First Draw. Corrosion. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.
A2SOM-03	Hallway, Left of Dining Room 202, Bottle Fill Water Cooler Outlet	BT	9:58 AM	5	ND	N	First Draw.
A2SOM-04	Hallway, Right of Boiler Room, Bubblers	B	10:05 AM	5	ND	N	First Draw. Corrosion.
A2SOM-05	Gym Entrance Door, Outside Men's Locker Room, Bubblers	B	Not Sampled				Out of Service. Did Not Sample.
A2SOM-06	Kitchen, 3-Compartment Sink, Left Faucet	KF	10:01 AM	5	ND	N	First Draw
A2SOM-07	Kitchen, 3-Compartment Sink, Right Faucet	KF	10:02 AM	5	ND	N	First Draw
A2SOM-08	Room 261, Faucet	C	10:22 AM	5	ND	N	First Draw
A2SOM-09	Room 261, Bubblers	C	10:22 AM	5	ND	N	First Draw
A2SOM-10	Hallway, Right of Room 311, Bubblers	B	10:14 AM	5	ND	N	First Draw. Corrosion.
A2SOM-11	Room 263, Faucet	C	10:19 AM	5	ND	Y	First Draw
A2SOM-12	Room 315, Kitchen Faucet	KF	10:14 AM	5	ND	Y	First Draw. Brita Filter on Faucet.
A2SOM-13	Room 306, Kitchen Faucet	KF	10:08 AM	5	25	Y	First Draw. Corrosion.
A2SOM-14	Hallway, Outside Room 302/304, Bubblers	B	10:09 AM	5	ND	N	First Draw. Corrosion.

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Ann Arbor Open School @ Mack							
Date of Sampling: 11/3/2018							
Sampler: Alec Staber							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
A2SOM-15	Hallway, In-between Room 303/305 , Bottle Fill Water Cooler Outlet	BT	10:16 AM	5	ND	N	First Draw.
A2SOM-16	Hallway, In-between Room 303/305, Bottle Fill Outlet	BT	10:11 AM	5	ND	N	First Draw.
A2SOM-17	Room 311, Faucet	F	10:13 AM	5	8	Y	First Draw. Paint Around Sink.
A2SOM-18	Fourth Floor, Faucet	F	Not Sampled				Out of Service. Did Not Sample.
A2SOM-19	Hallway, Outside Room 109B, Water Cooler	WC	9:56 AM	5	ND	N	First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.
A2SOM-20	Room 107, Bubbler	C	9:54 AM	5	3	N	First Draw. Corrosion.
A2SOM-21	Room 107, Faucet	C	9:55 AM	5	1	Y	First Draw
A2SOM-22	Room 201, Faucet	F	9:56 AM	5	ND	Y	First Draw
A2SOM-23	Staff Lounge, Faucet	F	10:03 AM	5	3	Y	First Draw
A2SOM-24	Clinic, Faucet	F	9:42 AM	5	4	N	First Draw. Corrosion.
A2SOM-25	Main Office, Faucet	F	9:41 AM	5	4	N	First Draw. Corrosion.
A2SOM-26	Room 213, Faucet	F	9:44 AM	5	43	N	First Draw. Corrosion, Slow Drain.
A2SOM-29	Room 233/235 Storage Closet, Faucet	F	10:55 AM	5	5	N	First Draw. Corrosion, Slow Drain.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L.
 4) NT = Not Tested



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Ann Arbor Open School @ Mack							
Date of Sampling: 11/3/2018							
Sampler: Alec Staber							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
A2SOM-30	Hallway, Left of Dining Room 202, Bottle Fill Outlet	BT	9:59 AM	5	ND	N	First Draw.
A2SOM-31	Pool Deck, Bubbler	B	Not Sampled				Not Accessible. Did Not Sample.
A2SOM-32	Room 233, Bubbler	C	Not Sampled				Out of Service. Did Not Sample.
A2SOM-33	Room 233, Faucet	C	10:54 AM	5	ND	Y	First Draw
A2SOM-34	Room 235, Bubbler	C	10:53 AM	5	ND	N	First Draw. Corrosion.
A2SOM-35	Room 235, Faucet	C	10:54 AM	5	2	Y	First Draw
A2SOM-36	Room 237, Bubbler	C	10:51 AM	5	ND	N	First Draw. Corrosion.
A2SOM-37	Room 237, Faucet	C	10:52 AM	5	ND	Y	First Draw
A2SOM-38	Room 239, Bubbler	C	10:48 AM	5	3	N	First Draw. Slow Drain.
A2SOM-39	Room 239, Faucet	C	10:49 AM	5	2	Y	First Draw. Slow Drain.
A2SOM-40	Room 241, Bubbler	C	10:46 AM	5	1	N	First Draw
A2SOM-41	Room 241, Faucet	C	10:47 AM	5	2	Y	First Draw
A2SOM-42	Room 243, Bubbler	C	10:44 AM	5	1	N	First Draw. Corrosion.
A2SOM-43	Room 243, Faucet	C	10:54 AM	5	ND	N	First Draw
A2SOM-44	Room 245, Bubbler	C	10:42 AM	5	2	N	First Draw. Corrosion.
A2SOM-45	Room 245, Faucet	C	10:43 AM	5	1	Y	First Draw
A2SOM-46	Room 247, Bubbler	C	10:40: AM	5	1	N	First Draw. Corrosion.
A2SOM-47	Room 247, Faucet	C	10:41 AM	5	ND	Y	First Draw
A2SOM-48	Room 249, Bubbler	C	10:37 AM	5	2	N	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Ann Arbor Open School @ Mack

Date of Sampling: 11/3/2018

Sampler: Alec Staber

Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
A2SOM-49	Room 249, Faucet	C	10:33 AM	5	2	Y	First Draw
A2SOM-50	Room 251, Bubblers	C	10:35 AM	5	ND	N	VOID SAMPLE
A2SOM-51	Room 251, Faucet	C	10:36 AM	5	ND	Y	VOID SAMPLE
A2SOM-52	Room 253, Bubblers	C	10:32 AM	5	1	N	First Draw
A2SOM-53	Room 253, Faucet	C	10:33 AM	5	1	Y	First Draw
A2SOM-54	Room 255, Bubblers	C	10:30 AM	5	2	N	First Draw. Slow Drain.
A2SOM-55	Room 255, Faucet	C	10:31 AM	5	1	N	First Draw. Slow Drain.
A2SOM-56	Room 257, Bubblers	C	10:28 AM	5	4	N	First Draw. Corrosion.
A2SOM-57	Room 257, Faucet	C	10:29 AM	5	4	N	First Draw
A2SOM-58	Room 259, Bubblers	C	10:25 AM	5	3	N	First Draw. Corrosion.
A2SOM-59	Room 259, Faucet	C	10:26 AM	5	5	N	First Draw. Corrosion.
A2SOM-60	Room 263, Bubblers	C	10:19 AM	5	1	N	First Draw. Corrosion.

Ann Arbor Open School @ Mack

Date of Sampling: 11/27/2018

Sampler: Alec Staber

Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
A2SOM-50	Room 251, Bubblers	C	6:13 AM	5	ND	N	First Draw
A2SOM-51	Room 251, Faucet	C	6:13 AM	5	2	Y	First Draw

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested