



Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Bryant-01	Hallway Outside Main Office, Left Water Cooler	WC	12:30 PM	5	1	N	First Draw. Corrosion on Mouthpiece. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.
Bryant-02	Teachers Lounge Sink Faucet	KF	12:37 PM	5	4	Y	First Draw
Bryant-03	Kitchen 3-Compartment Right Faucet	KF	12:35 PM	5	5	Y	First Draw
Bryant-04	Kitchen 3-Compartment Left Faucet	KF	12:35 PM	5	2	Y	First Draw
Bryant-05	Room 200, Bubbler	B	12:50 PM	5	5	N	First Draw
Bryant-06	Hallway Outside Room 203, Right Water Cooler	WC	Not Sampled.			N	Out of Service.
Bryant-07	Hallway Between Room 203 & 204, Bubbler	B	12:59 PM	5	2	N	First Draw
Bryant-08	Room 206, Bubbler	B	1:03 PM	5	2	N	First Draw
Bryant-09	Hallway Between Room 210 & 211, Bubbler	B	1:09 PM	5	1	N	First Draw
Bryant-10	Room 212, Bubbler	B	1:11 PM	5	4	N	First Draw
Bryant-11	Room 215, Bubbler	B	1:16 PM	5	4	N	First Draw
Bryant-12	Hallway Outside Exit Door 5 by Girls Bathroom, Right Water Cooler	WC	12:40 PM	5	2	N	First Draw. Corrosion on Mouthpiece. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Bryant-13	Hallway Outside Exit Door 5 by Girls Bathroom, Left Water Cooler	WC	12:40 PM	5	1	N	First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.
Bryant-14	Hallway between Room 217 & 218, Bubbler	B	1:20 PM	5	3	N	First Draw
Bryant-15	Hallway Between Room 208 & 209, Bubbler	B	1:07 PM	5	3	N	First Draw
Bryant-16	Room 216, Bubbler	B	1:18 PM	5	4	N	First Draw
Bryant-17	Room 207, Bubbler	B	1:05 PM	5	2	N	First Draw
Bryant-18	Room 205, Bubbler	B	1:01 PM	5	4	N	First Draw
Bryant-19	Room 214, Bubbler	B	1:15 PM	5	2	N	First Draw
Bryant-20	Hallway Outside Room 203, Bottle Fill, Water Cooler Outlet	BT	Not Sampled.			N	Out of Service.
Bryant-21	Room 213, Bubbler	B	1:13 PM	5	2	N	First Draw
Bryant-22	Hallway Outside Room 203, Bottle Fill Outlet	BT	Not Sampled.			N	Out of Service.
Bryant-23	Room 202, Bubbler	B	12:57 PM	5	1	N	First Draw
Bryant-24	Room 201, Bubbler	B	12:55 PM	5	5	N	First Draw
Bryant-25	Hallway, Near Library, Water Cooler	WC	1:21 PM	5	2	N	First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.
Bryant-26	Hallway Outside Main Office, Bottle Fill, Water Cooler Outlet	BT	12:31 PM	5	1	N	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminant>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Bryant-27	Hallway Outside Main Office, Bottle Fill Outlet	BT	12:31 PM	5	1	N	First Draw

Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Bryant-06	Hallway Outside Room 203, Right Water Cooler	WC	1:18 PM	5	1	N	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb