



Ann Arbor Public Schools
 Lead Drinking Water Analysis
 Project Number: AE180861

Burns Park Elementary School							
Date of Sampling: 11/10/2018							
Sampler: Steven Ripley							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Burns-01	Room 110, Bubbler	C	10:15 AM	5	3	N	First Draw
Burns-02	In Hallway, Outside Room 102, Bubbler	B	10:20 AM	5	ND ³	N	First Draw
Burns-03	In Hallway, Outside Kitchen, Bottle Fill	BT	10:44 AM	5	ND	N	First Draw
Burns-04	Room 213, Bubbler	C	11:30 AM	5	ND	N	First Draw. Low Flow.
Burns-05	In Hallway, Outside Media Center, Water Cooler	WC	11:39 AM	5	ND	N	First Draw. Corrosion on Mouthpiece. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.
Burns-06	Hallway, Outside Room 312, Bubbler	B	12:01 PM	5	ND	N	First Draw
Burns-07	Room 308, Faucet	F	12:25 PM	5	ND	Y	First Draw
Burns-08	Hallway, Outside Room 312	WC	N/A	5	N/A	N	Does Not Drain. Did Not Sample.
Burns-09	Room 103, Bubbler	C	10:40 AM	5	2	N	First Draw
Burns-10	Hallway, Outside Room 109, Bottle Fill, Water Cooler	BT	10:44 AM	5	ND	N	First Draw
Burns-11	Room A-6, Bubbler	C	11:16 AM	5	ND	N	First Draw
Burns-12	Room A-7, Bubbler	C	11:14 AM	5	ND	N	First Draw
Burns-13	Room A-7, Faucet	C	11:14 AM	5	ND	Y	First Draw
Burns-14	Room A-6, Faucet	C	11:16 AM	5	1	Y	First Draw. Corrosion at Faucet.
Burns-15	Room A-5 Bubbler	C	11:18 AM	5	ND	N	First Draw
Burns-16	Room A-5, Faucet	C	11:18 AM	5	ND	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminant>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



Ann Arbor Public Schools
 Lead Drinking Water Analysis
 Project Number: AE180861

Burns Park Elementary School							
Date of Sampling: 11/10/2018							
Sampler: Steven Ripley							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Burns-17	Room A-3, Bubbler	C	11:07 AM	5	ND	N	First Draw
Burns-18	Room A-3, Faucet	C	11:07 AM	5	5	Y	First Draw
Burns-19	Room A-1, Bubbler	C	N/A	5	N/A	N	Low Flow, Did Not Sample.
Burns-20	Room A-1, Faucet	C	10:59 AM	5	ND	Y	First Draw
Burns-21	Room A-4, Bubbler	C	11:10 AM	5	2	N	First Draw
Burns-22	Room A-4, Faucet	C	N/A	5	N/A	Y	Automatic Sink. Runs Warm Water. Did Not Sample.
Burns-23	Room A-2, Bubbler	C	11:01 AM	5	ND	N	First Draw. Corrosion On Bubbler.
Burns-24	Room A-2, Faucet	C	11:01 AM	5	1	Y	First Draw. Corrosion On Faucet.
Burns-25	Kitchen, 3-Compartment Faucet	KF	10:47 AM	5	ND	N	First Draw
Burns-26	Room 103, Faucet	C	10:41 AM	5	ND	Y	First Draw
Burns-27	Hallway, Outside Room 110, Bubbler	B	10:07 AM	5	ND	N	First Draw. Bubbler Drains Slow.
Burns-28	Room 101, Faucet	F	10:39 AM	5	ND	Y	First Draw
Burns-29	Room 102, Faucet	F	10:23 AM	5	13	Y	First Draw. Corrosion On Aerator.
Burns-30	Room 106, Faucet	F	10:17 AM	5	ND	Y	First Draw
Burns-31	Hallway, Outside Room 101, Bottle Fill	BT	10:36 AM	5	ND	N	First Draw
Burns-32	Room 110, Faucet	C	10:16 AM	5	1	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools
 Lead Drinking Water Analysis
 Project Number: AE180861

Burns Park Elementary School							
Date of Sampling: 11/10/2018							
Sampler: Steven Ripley							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Burns-33	Portable, Right Water Cooler	WC	11:33 AM	5	ND	N	First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.
Burns-34	Portable, Right Left Cooler	WC	11:34 AM	5	ND	N	First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.
Burns-35	Hallway, Outside Room 101, Bottle Fill, Water Cooler	BT	10:36 AM	5	ND	N	First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.
Burns-36	Room 213, Faucet	C	11:31 AM	5	ND	Y	First Draw
Burns-37	Room 209, Bubbler	C	11:35 AM	5	ND	N	First Draw
Burns-38	Room 209, Faucet	C	N/A	5	N/A	Y	Could Not Get Cold Water To Turn On, Did Not Sample.
Burns-39	Office 203, Clinic Faucet	F	11:37 AM	5	ND	Y	First Draw. Corrosion On Aerator.
Burns-40	Hallway, Outside Office 203, Bubbler	B	11:37 AM	5	2	N	First Draw
Burns-41	Media Center, Faucet	F	11:41 AM	5	8	Y	First Draw
Burns-42	Room 307, Bubbler	C	12:22 PM	5	ND	N	First Draw
Burns-43	Room 307, Faucet	C	12:22 PM	5	1	Y	First Draw
Burns-44	Hallway, Outside Room 301, Bottle Fill	BT	12:20 PM	5	ND	N	First Draw
Burns-45	Hallway, Outside Room 301, Bottle Fill, Water Cooler	BT	12:19 PM	5	ND	N	First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested