



Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Clague-01	Main Entrance, Outside Main Office, Water Cooler	WC	Not Sampled				Scheduled to be replaced with a Hydration Station.
Clague-02	Hallway, Outside Room 146, Left of Elevator, Water Cooler	WC	Not Sampled				Scheduled to be replaced with a Hydration Station.
Clague-03	Cafeteria, Hydration Station Water Cooler	BT	10:50 AM	5	ND ³	N	First Draw
Clague-04	Kitchen, 3-Compartment Sink, Middle Faucet	KF	10:00 AM	5	3	N	First Draw
Clague-05	Kitchen, 3-Compartment Sink, Left Faucet	KF	10:00 AM	5	ND	N	First Draw
Clague-06	Hallway Outside Pool, Water Cooler	WC	Not Sampled				Scheduled to be replaced with a Hydration Station.
Clague-07	Hallway, to the Left of Laundry Room by Gym, Hydration Station Water Cooler	WC	10:27 AM	5	ND	N	First Draw
Clague-08	Hallway, Outside Room 229 and Elevator, Water Cooler	WC	Not Sampled				Scheduled to be replaced with a Hydration Station.
Clague-09	Room 228, Right Single Sink Faucet	F	11:15 AM	5	8	Y	First Draw
Clague-10	Room 226, Faucet	F	Not Sampled				Push down fixture, only hot water.
Clague-11	Hallway, Outside Room 223, Water Cooler	WC	Not Sampled				Scheduled to be replaced with a Hydration Station.
Clague-12	OPEN NUMBER						
Clague-13	OPEN NUMBER						
Clague-14	OPEN NUMBER						

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Clague-15	Room 223, Music Room Faucet	F	11:20 AM	5	6	Y	First Draw
Clague-16	OPEN NUMBER						
Clague-17	Dressing Room, Right Faucet	F	Not Sampled				Out of Service.
Clague-18	Dressing Room, Left Faucet	F	Not Sampled				Out of Service.
Clague-19	Room 228, Left Single Sink Faucet	F	11:17 AM	5	24	Y	First Draw, Corrosion.
Clague-20	Room 229, Faucet	F	11:10 AM	5	15	N	First Draw, Corrosion.
Clague-21	Room 230, Faucet	F	11:13 AM	5	5	Y	First Draw
Clague-22	Room 230, Faucet	F	11:13 AM	5	5	Y	First Draw
Clague-23	Hallway, Outside Room 204, Water Cooler	WC	Not Sampled				Scheduled to be replaced with a Hydration Station.
Clague-24	Second Floor Teacher's Lounge, Faucet	F	11:30 AM	5	4	Y	First Draw
Clague-25	Hallway Outside Room 208, Water Cooler	WC	Not Sampled				Scheduled to be replaced with a Hydration Station.
Clague-26	Room 208, Faucet	F	11:28 AM	5	110	Y	First Draw
Clague-27	Hallway Outside Room 216, Water Cooler	WC	Not Sampled				Scheduled to be replaced with a Hydration Station.
Clague-28	Hallway, to the Left of Laundry Room by Gym, Hydration Station Bottle Fill	BT	11:28 AM	5	ND		First Draw
Clague-29	Gym, South Corner, Bubbler	B	10:34 AM	5	1		First Draw, Corrosion.
Clague-30	Gym, North Corner, Water Cooler	WC	10:32 AM	5	2		First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes	
Clague-31	Room 146, Conference Room Faucet	F	9:53 AM	5	21	N	First Draw	
Clague-32	Cafeteria, Hydration Station Bottle Fill	BT	10:50 AM	5	ND		First Draw	
Clague-33	Kitchen, 3-Compartment Sink, Right Faucet	KF	9:59 AM	5	110	N	First Draw	
Clague-34	Girl's Locker Room, Water Cooler	WC	10:44 AM	5	ND		First Draw, Corrosion.	
Clague-35	Boy's Locker Room, Water Cooler	WC	10:38 AM	5	ND		First Draw, Corrosion.	
Clague-36	Room 143, Faucet	F	10:22 AM	5	2	Y	First Draw	
Clague-37	Kitchen, Singular Central Sink, Faucet	KF	9:57 AM	5	42	N	First Draw	
Clague-38	Hallway, Outside room 144, Water Cooler	WC	Not Sampled					Scheduled to be replaced with a Hydration Station.
Clague-39	Pool, South wall, Right Bubbler	B	10:40 AM	5	3		First Draw	
Clague-40	Pool, South Wall, Left Bubbler	B	10:42 AM	5	22		First Draw	
Clague-41	Room 140, Water Cooler	WC	10:47 AM	5	18		First Draw	
Clague-42	"Blue House" Room, West of Room 136, Faucet	F	10:52 AM	5	13	N	First Draw	
Clague-43	Hallway, Outside Room 131, Water Cooler	WC	Not Sampled					Scheduled to be replaced with a Hydration Station.
Clague-44	OPEN NUMBER							
Clague-45	Hallway, Outside Room 124, Water Cooler	WC	Not Sampled					Scheduled to be replaced with a Hydration Station.
Clague-46	Media Center Work Room, Faucet	F	10:56 AM	5	12		First Draw	

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Clague-47	Hallway, Outside Main Offices, Water Cooler	WC	Not Sampled				Scheduled to be replaced with a Hydration Station.
Clague-48	Clinic, Faucet	F	11:04 AM	5	5	Y	First Draw
Clague-49	Room 141, First End Sink Closest to the entry door.	KF	10:07 AM	5	4	N	First Draw
Clague-50	Room 141, Second Middle Sink Closest to the entry door.	KF	10:07 AM	5	3	N	First Draw, Corrosion.
Clague-51	Room 141, Third Middle Sink Farthest From the entry door.	KF	10:08 AM	5	4	N	First Draw
Clague-52	Room 141, Fourth End Sink Farthest from the entry door.	KF	10:09 AM	5	4	N	First Draw
Clague-53	Room 142, First Sink Closest to the Entry Door	KF	10:15 AM	5	11	N	First Draw, Corrosion.
Clague-54	Room 142, Second Sink From the Entry Door	KF	Not Sampled				Cold water out of service, hot only.
Clague-55	Room 142, Third Sink From the Entry Door	KF	10:16 AM	5	3	N	First Draw
Clague-56	Room 142, Fourth Sink From the Entry Door	KF	10:17 AM	5	4	N	First Draw, Corrosion.
Clague-57	Room 142, Fifth Sink From the Entry Door	KF	10:18 AM	5	4	N	First Draw, Corrosion.
Clague-58	Room 142, Sixth Sink From the Entry Door	KF	Not Sampled				Cold water out of service, hot only.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb