



st

st							
st							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Forsythe-06	Room 103 Faucet	F	1:18 PM	5	9	N	First Draw, Corrosion.
Forsythe-26	Room 312, Second Island Sink Group from the Door, Left Faucet	F	2:03 PM	5	6	Y	First Draw
Forsythe-27	Room 312, Second Island Sink Group from the Door, Right Faucet	F	2:04 PM	5	11	Y	First Draw
Forsythe-34	Pool, Bubbler	B	1:38 PM	5	200	N	First Draw. Observed Corrosion and Cloudy Water.

st							
st							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Forsythe-06	Room 103 Faucet	F	11:28 AM	5	27	N	2nd Follow-up first draw following replacement activities.
Forsythe-26	Room 312, Second Island Sink Group from the Door, Left Faucet	F	11:38 AM	5	16	Y	2nd Follow-up first draw following replacement activities.
Forsythe-27	Room 312, Second Island Sink Group from the Door, Right Faucet	F	11:42 AM	5	6	Y	2nd Follow-up first draw following replacement activities.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



st

st							
st							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Forsythe-34	Pool, Bubblers	B	11:53 AM	5	300	N	2nd Follow-up first draw following replacement activities.

st							
st							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Forsythe-06	Room 103 Faucet	F	2:40 PM	5	8	N	3rd Follow-up first draw following replacement activities.
Forsythe-26	Room 312, Second Island Sink Group from the Door, Left Faucet	F	2:59 PM	5	10	Y	3rd Follow-up first draw following replacement activities.
Forsythe-27	Room 312, Second Island Sink Group from the Door, Right Faucet	F	2:57 PM	5	52	Y	3rd Follow-up first draw following replacement activities.
Forsythe-34	Pool, Bubblers	B	2:50 PM	5	ND		3rd Follow-up first draw following replacement activities.

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminant>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



st

st							
st							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Forsythe-06	Room 103 Faucet	F	10:00 AM	5	2	N	4th Follow-up first draw following replacement activities.
Forsythe-26	Room 312, Second Island Sink Group from the Door, Left Faucet	F	10:07 AM	5	9	Y	4th Follow-up first draw following replacement activities.
Forsythe-27	Room 312, Second Island Sink Group from the Door, Right Faucet	F	10:08 AM	5	2	Y	4th Follow-up first draw following replacement activities.

st							
st							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Forsythe-26	Room 312, Second Island Sink Group from the Door, Left Faucet	F	9:45 AM	5	5	Y	5th Follow-up first draw following replacement activities.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb