



**Ann Arbor Public Schools  
Lead Drinking Water Analysis  
Project Number: AE180861**

Lawton Elementary School							
Date of Sampling: 10/13/18							
Sampler: Lauren Koloski							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-13	Room 312, Bubbler	C	11:54 AM	5	123	N	First Draw. Bubbler was observed bagged. This location was out of service prior to sampling for an unknown period of time. Likely stagnant water.
Lawton-14	Room 314, Bubbler	C	11:51 AM	5	6	N	First Draw. Faucet has a drip.
Lawton-16	Room 308, Bubbler	C	11:57 AM	5	7	N	First Draw

Lawton Elementary School							
Date of Sampling: 10/20/18							
Sampler: Jenna Sendra							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-46	Room 308 Faucet	C	7:57 AM	5	14	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools  
Lead Drinking Water Analysis  
Project Number: AE180861**

Lawton Elementary School							
Date of Sampling: 10/27/18							
Sampler: Jenna Sendra							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-04	Room 314, Faucet	C	11:51 AM	5	21	N	First Draw. Faucet Drips.

Lawton Elementary School							
Date of Sampling: 12/22/18							
Sampler: Jenna Sendra							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-04A	Room 314, Faucet	C	6:50 AM	5	3	N	Follow-Up First Draw Following Replacement
Lawton-13A	Room 312, Bubbler	C	7:04 AM	5	18	N	Follow-Up First Draw Following Replacement
Lawton-14A	Room 314, Bubbler	C	6:48 AM	5	1	N	Follow-Up First Draw Following Replacement
Lawton-16A	Room 308, Bubbler	C	7:07 AM	5	13	N	Follow-Up First Draw Following Replacement
Lawton-46A	Room 308 Faucet	C	7:07 AM	5	92	Y	Follow-Up First Draw Following Replacement

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools  
Lead Drinking Water Analysis  
Project Number: AE180861**

Lawton Elementary School							
Date of Sampling: 01/12/19							
Sampler: Jenna Sendra							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-16B	Room 308, Bubbler	C	10:25 AM	5	ND	N	2nd Follow-Up First Draw Following Replacement. New filter added.
Lawton-46B	Room 308 Faucet	C	10:26 AM	5	ND	Y	2nd Follow-Up First Draw Following Replacement. New filter added.

Lawton Elementary School							
Date of Sampling: 01/17/19							
Sampler: Jenna Sendra							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-13B	Room 312, Bubbler	C	6:34 AM	5	ND	N	2nd Follow-Up First Draw Following Replacement. New filter added.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested