



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Lawton Elementary School							
Date of Sampling: 10/13/18							
Sampler: Lauren Koloski							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-02	Room 312, Faucet	C	11:54 AM	5	5	Y	First Draw
Lawton-13	Room 312, Bubbler	C	11:54 AM	5	123	N	First Draw. Bubbler was observed bagged. This location was out of service prior to sampling for an unknown period of time. Likely stagnant water.
Lawton-14	Room 314, Bubbler	C	11:51 AM	5	6	N	First Draw. Faucet has a drip.
Lawton-15	Room 313, Kitchen Faucet	KF	11:52 AM	5	3	Y	First Draw. Scale around cold water handle.
Lawton-16	Room 308, Bubbler	C	11:57 AM	5	7	N	First Draw
Lawton-17	Room 305, Bubbler	C	11:58 AM	5	2	N	First Draw
Lawton-18	Room 304, Bubbler	C	12:00 PM	5	2	N	First Draw
Lawton-19	Room 303, Bubbler	C	12:01 PM	5	2	N	First Draw
Lawton-20	Room 302, Bubbler	C	12:03 PM	5	2	N	First Draw
Lawton-21	Room 301, Bubbler	C	12:04 PM	5	1	N	First Draw
Lawton-23	Room 209, Bubbler	C	11:24 AM	5	1	N	First Draw
Lawton-24	Room 208, Bubbler	C	11:23 AM	5	1	N	First Draw. Rust around bubbler mouthpiece.
Lawton-25	Cafeteria, Hydration Station Bottle Fill	BT	10:55 AM	5	ND ³	N	First Draw
Lawton-26	Cafeteria, Hydration Station Water Cooler	BT	10:55 AM	5	2	N	First Draw.
Lawton-28	Kitchen, Single Sink, Faucet	KF	10:58 AM	5	2	Y	First Draw
Lawton-29	Room 204, Bubbler	C	11:04 AM	5	2	N	First Draw
Lawton-30	Room 202, Bubbler	C	10:55 AM	5	2	N	First Draw
Lawton-31	Room 201, Bubbler	C	11:08 AM	5	ND	N	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Lawton Elementary School							
Date of Sampling: 10/13/18							
Sampler: Lauren Koloski							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-32	Room 101, Bubblers	C	11:12 AM	5	2	N	First Draw
Lawton-33	Room 102, Bubblers	C	11:35 AM	5	1	N	First Draw
Lawton-34	Main Office, Kitchen Faucet	KF	11:16 AM	5	5	Y	First Draw
Lawton-35	Hallway Outside Room 101, Hydration Station Bottle Fill	BT	11:09 AM	5	1	N	First Draw
Lawton-36	Hallway Outside Room 101, Hydration Station Water Cooler	BT	11:09 AM	5	1	N	First Draw
Lawton-37	Hallway Outside Room 114, Hydration Station Bottle Fill	BT	11:29 AM	5	2	N	First Draw
Lawton-38	Hallway Outside Room 114, Hydration Station Water Cooler	BT	11:29 AM	5	ND	N	First Draw
Lawton-40	Room 109, Bubblers	C	11:40 AM	5	1	N	First Draw
Lawton-41	Room 108, Bubblers	C	11:37 AM	5	ND	N	First Draw
Lawton-42	Room 107, Bubblers	C	11:36 AM	5	ND	N	First Draw
Lawton-43	Room 106, Bubblers	C	11:34 AM	5	ND	N	First Draw

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Lawton Elementary School							
Date of Sampling: 10/20/18							
Sampler: Jenna Sendra							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-12	Room 210, Faucet	C	7:09 AM	5	2	Y	First Draw
Lawton-22	Room 204, Faucet	C	6:41 AM	5	3	Y	First Draw
Lawton-27	Kitchen 3-Compartment, Right Faucet	KF	8:15 AM	5	3	Y	First Draw
Lawton-39	Room 209, Faucet	C	6:56 AM	5	ND	Y	First Draw
Lawton-44	Room 310, Faucet	C	7:54 AM	5	2	Y	First Draw
Lawton-45	Room 316, Faucet	C	7:50 AM	5	2	Y	First Draw
Lawton-46	Room 308 Faucet	C	7:57 AM	5	14	Y	First Draw
Lawton-48	Room 305, Faucet	C	7:58 AM	5	2	Y	First Draw
Lawton-49	Room 304, Faucet	C	8:03 AM	5	2	Y	First Draw
Lawton-50	Room 303, Faucet	C	8:05 AM	5	2	Y	First Draw
Lawton-51	Room 302, Faucet	C	8:07 AM	5	2	Y	First Draw
Lawton-52	Room 301, Faucet	C	8:10 AM	5	1	Y	First Draw
Lawton-53	Room 109, Faucet	C	7:04 AM	5	ND	Y	First Draw
Lawton-54	Room 108, Faucet	C	7:07 AM	5	ND	N	First Draw. Faucet has a drip.
Lawton-55	Room 107, Faucet	C	7:10 AM	5	1	Y	First Draw
Lawton-56	Room 106, Faucet	C	7:12 AM	5	1	Y	First Draw
Lawton-57	Room 208, Faucet	C	6:54 AM	5	ND	Y	First Draw
Lawton-58	Main Office Nurse's Faucet	F	7:15 AM	5	3	Y	First Draw
Lawton-59	Room 102 Faucet	C	7:18 AM	5	2	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861

Lawton Elementary School							
Date of Sampling: 10/20/18							
Sampler: Jenna Sendra							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-60	Room 101, Faucet	C	7:19 AM	5	2	Y	First Draw
Lawton-61	Room 202, Faucet	C	6:49 AM	5	ND	N	First Draw
Lawton-62	Room 203, Faucet	C	6:46 AM	5	1	N	First Draw
Lawton-63	Room 101, Faucet	F	7:20 AM	5	2	Y	First Draw
Lawton-64	Room 201, Faucet	F	7:40 AM	5	1	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Lawton Elementary School							
Date of Sampling: 10/27/18							
Sampler: Jenna Sendra							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-01	Room 310, Bubblers	C	11:47 AM	5	2	N	First Draw
Lawton-03	Room 316, Bubblers	C	11:49 AM	5	2	N	First Draw
Lawton-04	Room 314, Faucet	C	11:51 AM	5	21	N	First Draw. Faucet Drips.
Lawton-05	Room 210, Bubblers	C	11:54 AM	5	2	N	First Draw
Lawton-06	Cafeteria/Auditorium, Right Water Cooler	WC	12:01 PM	5	ND	N	First Draw
Lawton-07	Kitchen, 3-Compartment, Left Faucet	KF	11:59 AM	5	3	Y	First Draw
Lawton-08	Gym, Bubblers	B	11:45 AM	5	ND	N	First Draw. Staining Around Mouthpiece.
Lawton-09	Room 218, Faucet	C	11:57 AM	5	1	N	First Draw
Lawton-10	Room 203, Bubblers	B	12:03 PM	5	2	N	First Draw
Lawton-11	Room 201, Faucet	C	12:05 PM	5	ND	Y	First Draw
Lawton-65	Room 218, Bubblers	C	11:56 AM	5	ND	N	First Draw

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Lawton Elementary School							
Date of Sampling: 01/12/19							
Sampler: Jenna Sendra							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-67	Hallway Outside Room 301, Hydration Station Water Cooler	BF	10:32 AM	5	ND	N	First Draw. Newly installed Bottle Fill.
Lawton-68	Hallway Outside Room 312, Hydration Station Bottle Fill	BF	10:14 AM	5	ND	N	First Draw. Newly installed Bottle Fill.
Lawton-69	Hallway Outside Room 312, Hydration Station Water Cooler	BF	10:14 AM	5	ND	N	First Draw. Newly installed Bottle Fill.

Lawton Elementary School							
Date of Sampling: 01/17/19							
Sampler: Jenna Sendra							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Lawton-66	Hallway Outside Room 301, Hydration Station Bottle Fill	BF	6:36 AM	5	ND	N	First Draw. Newly installed Bottle Fill.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminant>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested