



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Logan Elementary School							
Date of Sampling: 11/17/2018							
Sampler: Lauren Koloski							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Logan ES-02	Teacher's Lounge, Faucet	KF	7:24 AM	5	6	Y	First Draw
Logan ES-10	Room 240, Bubbler	C	7:52 AM	5	7	N	First Draw
Logan ES-11	Room 234, Faucet	C	8:01 AM	5	6	Y	First Draw
Logan ES-13	Room 324, Faucet	C	8:17 AM	5	6	N	First Draw. Corrosion Around Handles.
Logan ES-15	Room 326, Faucet	C	8:20 AM	5	9	Y	First Draw. Corrosion Around Handles.
Logan ES-17	Room 328, Faucet	C	8:22 AM	5	38	Y	First Draw
Logan ES-19	Room 330, Faucet	C	8:25 AM	5	7	Y	First Draw
Logan ES-21	Room 332, Faucet	C	8:27 AM	5	9	Y	First Draw
Logan ES-27	Room 212, Faucet	C	8:15 AM	5	8	Y	First Draw
Logan ES-30	Room 224, Faucet	C	8:10 AM	5	8	Y	First Draw. Scale and Corrosion Around Handle and Aerator.
Logan ES-36	Room 236, Bubbler	C	8:00 AM	5	6	N	First Draw
Logan ES-37	Room 236, Faucet	C	8:00 AM	5	7	Y	First Draw. Corrosion on Aerator.
Logan ES-39	Room 238, Faucet	C	7:55 AM	5	42	Y	First Draw
Logan ES-40	Room 240, Faucet	C	7:52 AM	5	11	Y	First Draw. Build-up on Aerator.
Logan ES-42	Room 241, Faucet	C	7:50 AM	5	12	Y	First Draw
Logan ES-43	Room 243, Bubbler	C	7:45 AM	5	7	N	First Draw
Logan ES-44	Room 243, Faucet	C	7:45 AM	5	9	Y	First Draw
Logan ES-45	Room 250, Bubbler	C	7:42 AM	5	7	N	First Draw
Logan ES-46	Room 250, Faucet	C	7:42 AM	5	22	Y	First Draw. Corrosion on Aerator.
Logan ES-47	Room 253, Bubbler	C	7:38 AM	5	9	N	First Draw. Low Flow.
Logan ES-48	Room 253, Faucet	C	7:38 AM	5	13	Y	First Draw. Corrosion on Aerator.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Logan Elementary School							
Date of Sampling: 12/08/2018							
Sampler: Steven Ripley							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Logan ES-10A	Room 240, Bubbler	C	12:40 PM	5	6	N	Follow-up First Draw Following Replacement
Logan ES-17A	Room 328, Faucet	C	12:35 PM	5	8	Y	Follow-up First Draw Following Replacement
Logan ES-36A	Room 236, Bubbler	C	12:30 PM	5	3	N	Follow-up First Draw Following Replacement
Logan ES-39A	Room 238, Faucet	C	12:20 PM	5	210	Y	Follow-up First Draw Following Replacement
Logan ES-43A	Room 243, Bubbler	C	12:10 PM	5	9	N	Follow-up First Draw Following Replacement
Logan ES-44A	Room 243, Faucet	C	12:10 PM	5	10	Y	Follow-up First Draw Following Replacement
Logan ES-45A	Room 250, Bubbler	C	11:49 AM	5	11	N	Follow-up First Draw Following Replacement
Logan ES-46A	Room 250, Faucet	C	11:49 AM	5	16	Y	Follow-up First Draw Following Replacement
Logan ES-47A	Room 253, Bubbler	C	12:04 PM	5	7	N	Follow-up First Draw Following Replacement
Logan ES-48A	Room 253, Faucet	C	12:04 PM	5	95	Y	Follow-up First Draw Following Replacement

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Logan Elementary School							
Date of Sampling: 12/22/2018							
Sampler: Gary Bosh							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Logan ES-02A	Teacher's Lounge, Faucet	KF	8:47 AM	5	16	Y	Follow-Up First Draw Following Replacement
Logan ES-10B	Room 240, Bubbler	C	8:32 AM	5	5	N	2nd Follow-Up First Draw Following Replacement
Logan ES-11A	Room 234, Faucet	C	8:16 AM	5	13	Y	Follow-Up First Draw Following Replacement
Logan ES-13A	Room 324, Faucet	C	8:50 AM	5	27	N	Follow-Up First Draw Following Replacement
Logan ES-15A	Room 326, Faucet	C	8:53 AM	5	17	Y	Follow-Up First Draw Following Replacement
Logan ES-17B	Room 328, Faucet	C	8:54 AM	5	8	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-19A	Room 330, Faucet	C	8:56 AM	5	18	Y	Follow-Up First Draw Following Replacement
Logan ES-21A	Room 332, Faucet	C	9:00 AM	5	49	Y	Follow-Up First Draw Following Replacement
Logan ES-27A	Room 212, Faucet	C	8:13 AM	5	19	Y	Follow-Up First Draw Following Replacement
Logan ES-30A	Room 224, Faucet	C	8:15 AM	5	12	Y	Follow-Up First Draw Following Replacement
Logan ES-37A	Room 236, Faucet	C	8:29 AM	5	10	Y	Follow-Up First Draw Following Replacement
Logan ES-39B	Room 238, Faucet	C	8:30 AM	5	8	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-40A	Room 240, Faucet	C	8:31 AM	5	20	Y	Follow-Up First Draw Following Replacement
Logan ES-42A	Room 241, Faucet	C	8:36 AM	5	9	Y	Follow-Up First Draw Following Replacement
Logan ES-43B	Room 243, Bubbler	C	8:37 AM	5	9	N	2nd Follow-Up First Draw Following Replacement
Logan ES-44B	Room 243, Faucet	C	8:38 AM	5	21	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-45B	Room 250, Bubbler	C	8:40 AM	5	6	N	2nd Follow-Up First Draw Following Replacement
Logan ES-46B	Room 250, Faucet	C	8:41 AM	5	8	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-47B	Room 253, Bubbler	C	8:43 AM	5	6	N	2nd Follow-Up First Draw Following Replacement
Logan ES-48B	Room 253, Faucet	C	8:46 AM	5	7	Y	2nd Follow-Up First Draw Following Replacement

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Logan Elementary School							
Date of Sampling: 02/02/2019							
Sampler: Alec Staber							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Logan ES-02B	Teacher's Lounge, Faucet	KF	9:05 AM	5	13	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-11B	Room 234, Faucet	C	1:30 PM	5	5	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-13B	Room 324, Faucet	C	12:33 PM	5	1	N	2nd Follow-Up First Draw Following Replacement
Logan ES-15B	Room 326, Faucet	C	12:38 PM	5	ND	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-17C	Room 328, Faucet	C	12:48 PM	5	1	Y	3rd Follow-Up First Draw Following Replacement
Logan ES-19B	Room 330, Faucet	C	12:51 PM	5	2	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-21B	Room 332, Faucet	C	12:55 PM	5	110	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-27B	Room 212, Faucet	C	1:08 PM	5	1	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-30B	Room 224, Faucet	C	1:20 PM	5	39	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-37B	Room 236, Faucet	C	1:36 PM	5	3	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-39C	Room 238, Faucet	C	1:39 PM	5	ND	Y	3rd Follow-Up First Draw Following Replacement
Logan ES-40B	Room 240, Faucet	C	1:42 PM	5	4	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-42B	Room 241, Faucet	C	1:30 PM	5	ND	Y	2nd Follow-Up First Draw Following Replacement
Logan ES-43C	Room 243, Bubbler	C	1:54 PM	5	2	N	3rd Follow-Up First Draw Following Replacement
Logan ES-44C	Room 243, Faucet	C	1:54 PM	5	54	Y	3rd Follow-Up First Draw Following Replacement
Logan ES-45C	Room 250, Bubbler	C	1:59 PM	5	ND	N	3rd Follow-Up First Draw Following Replacement
Logan ES-46C	Room 250, Faucet	C	1:59 PM	5	7	Y	3rd Follow-Up First Draw Following Replacement
Logan ES-47C	Room 253, Bubbler	C	2:02 PM	5	ND	N	3rd Follow-Up First Draw Following Replacement
Logan ES-48C	Room 253, Faucet	C	2:02 PM	5	ND	Y	3rd Follow-Up First Draw Following Replacement

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Logan Elementary School							
Date of Sampling: 02/16/2019							
Sampler: Steven Ripley							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Logan ES-02C	Teacher's Lounge, Faucet	KF	10:00 AM	5	2	Y	3rd Follow-Up First Draw Following Replacement
Logan ES-21C	Room 332, Faucet	C	10:05 AM	5	5	Y	3rd Follow-Up First Draw Following Replacement
Logan ES-30C	Room 224, Faucet	C	10:08 AM	5	35	Y	3rd Follow-Up First Draw Following Replacement
Logan ES-44D	Room 243, Faucet	C	10:10 AM	5	3	Y	4th Follow-Up First Draw Following Replacement
Logan ES-46D	Room 250, Faucet	C	10:10 AM	5	4	Y	4th Follow-Up First Draw Following Replacement

Logan Elementary School							
Date of Sampling: 02/23/2019							
Sampler: Lindsey Eveleth							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Logan ES-30D	Room 224, Faucet	C	10:08 AM	5	1	Y	4th Follow-Up First Draw Following Replacement

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested