



Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861

Pioneer Middle School							
Date of Sampling: March 29, 2019							
Sampler: Amanda Peterson							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pioneer-01	Hallway Outside Small Theater, Bubbler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-02	Hallway, Left of Auditorium, Single Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-03	Hallway, Outside Room B-116, Bubbler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-04	Hallway, Right of Auditorium, Hydration Station, Water Cooler	BF	1:32 PM	5	ND ³	N	First Draw
Pioneer-05	Hallway, Right of Auditorium, Hydration Station, Bottle Fill	BF	1:34 PM	5	1	N	First Draw
Pioneer-06	Media Center, Left Hydration Station, Water Cooler	BF	3:00 PM	5	ND	N	First Draw
Pioneer-07	Hallway, Southeast Wing, Floor 1, Outside of Media Center, Left Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-08	Hallway, Northwest Wing, Outside of Cafeteria, Left Hydration Station, Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-09	Hallway, Northwest Wing, Outside of Cafeteria, Left Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-10	Hallway Outside Room C-214, Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-11	Hallway, Outside Room C-310, Hydration Station, Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-12	Hallway, Outside Room C-322, Hydration Station, Water Cooler	BF	3:20 PM	5	1	N	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861

Pioneer Middle School							
Date of Sampling: March 29, 2019							
Sampler: Amanda Peterson							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pioneer-13	Hallway, Outside Room C-304, Hydration Station, Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-14	Hallway, Outside Room C-304, Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-15	Main Gym, Near North Entrance, Bubbler	B	1:50 PM	5	3	N	First Draw, Corrosion noted on mouthpiece
Pioneer-16	Main Gym, Near South Entrance, Bubbler	B	1:52 PM	5	20	N	First Draw, Corrosion noted on mouthpiece as well as lower than average flow
Pioneer-17	Pool Deck, Bubbler on West Wall	B	2:02 PM	5	7	N	First Draw, Corrosion noted on mouthpiece
Pioneer-18	Pool Deck, Bubbler on East Wall	B	2:00 PM	5	3	N	First Draw, Corrosion noted on mouthpiece
Pioneer-19	Auxiliary Gym, Bubbler Outside Boy's Locker Room	B	1:36 PM	5	6	N	First Draw, Yellow tint to flow noted
Pioneer-20	Auxiliary Gym, Bubbler Outside Girl's Locker Room	B	1:38 PM	5	2	N	First Draw
Pioneer-21	Boy's Auxiliary Gym Locker Room, Bubbler	B	1:40 PM	5	3	N	First Draw, Corrosion noted on mouthpiece
Pioneer-22	Girl's Auxiliary Gym Locker Room, West Bubbler	B	1:42 PM	5	8	N	First Draw, cloudy rusty flow noted
Pioneer-23	Girl's Auxiliary Gym Locker Room, East Bubbler	B	1:44 PM	5	3	N	First Draw, cloudy flow noted

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools
 Lead Drinking Water Analysis
 Project Number: AE180861

Pioneer Middle School							
Date of Sampling: March 29, 2019							
Sampler: Amanda Peterson							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pioneer-24	Room A-131, Ice Machine	I	2:20 PM	5	1	N	First Draw
Pioneer-25	Room A-131, Single Sink Faucet	F	2:22 PM	5	3	Y	First Draw
Pioneer-26	Room A-131, Single Bubbler	Not Sampled, No Water to Fixture					
Pioneer-29	Main Office Suite, Infirmary S-174, Second Faucet	F	2:30 PM	5	3	Y	First Draw, Corrosion noted on mouthpiece
Pioneer-30	Main Office Suite, Infirmary S-174, Front Faucet	F	2:32 PM	5	1	Y	First Draw, Corrosion noted on mouthpiece
Pioneer-31	Main Office Suite, Staff Kitchen S105, Faucet	KF	2:48 PM	5	1	Y	First Draw
Pioneer-32	Hallway, Main Office Suite, Hydration Station, Water Cooler	BF	2:44 PM	5	ND	N	First Draw
Pioneer-33	Hallway, Main Office Suite, Hydration Station, Bottle Fill	BF	2:46 PM	5	ND	Y	First Draw
Pioneer-34	Cafeteria, Water Cooler	WC	3:02 PM	5	ND	N	First Draw, Corrosion noted on mouthpiece
Pioneer-35	Kitchen, Single Compartment Sink, Across from Two Compartment Sink	KF	3:16 PM	5	ND	Y	First Draw
Pioneer-36	Kitchen, Single Compartment Sink, Next to Coffee Machine	KF	3:18 PM	5	1	Y	First Draw
Pioneer-37	Kitchen, Plumbed Coffee Machine	PC	3:19 PM	5	ND	N	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumbed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools
 Lead Drinking Water Analysis
 Project Number: AE180861

Pioneer Middle School							
Date of Sampling: March 29, 2019							
Sampler: Amanda Peterson							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pioneer-38	OPEN NUMBER						
Pioneer-39	Kitchen, Two Compartment Sink, Faucet	KF	3:20 PM	5	2	N	First Draw
Pioneer-40	Kitchen, Plumbed Kettle	Not Sampled, No Water to Fixture					
Pioneer-41	Kitchen, Ice Machine	I	3:10 PM	5	1	N	First Draw
Pioneer-43	Kitchen, Three Compartment Sink, Left Faucet	KF	3:12 PM	5	ND	N	First Draw
Pioneer-44	Kitchen, Three Compartment Sink, Right Faucet	KF	3:14 PM	5	2	N	First Draw
Pioneer-45	Room C-110, Faucet	F	2:50 PM	5	3	Y	First Draw
Pioneer-46	Hallway, Outside Room C-110, Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-47	Hallway, Outside Room C-116, Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-48	Hallway, Outside Room C-126, Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-49	Hallway, Outside Room E-101, Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-50	Teacher's Lounge, Kitchen Faucet	KF	3:04 PM	5	4	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumbed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools
 Lead Drinking Water Analysis
 Project Number: AE180861

Pioneer Middle School							
Date of Sampling: March 29, 2019							
Sampler: Amanda Peterson							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pioneer-51	Room E-110, Faucet	F	3:46 PM	5	1	Y	First Draw
Pioneer-52	Room E-108, Faucet	F	3:44 PM	5	1	Y	First Draw
Pioneer-53	Hallway, Outside Room E-112, Right Hydration Station, Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-54	Hallway, Outside Room E-112, Right Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-55	Hallway, Outside Room E-112, Left Hydration Station, Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-56	Hallway, Outside Room E-112, Left Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-57	Lower Level Track/Weight Room, Hydration Station, Water Cooler	BF	3:30 PM	5	ND	N	First Draw
Pioneer-58	Lower Level Track/Weight Room, Hydration Station, Bottle Fill	BF	3:31 PM	5	ND	Y	First Draw
Pioneer-59	Hallway, Outside Room C-206, Hydration Station, Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-60	Hallway, Outside Room C-206, Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-61	Hallway, Outside Room C-214, Hydration Station, Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-62	Hallway, Outside Room C-231, Hydration Station, Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



Ann Arbor Public Schools
 Lead Drinking Water Analysis
 Project Number: AE180861

Pioneer Middle School							
Date of Sampling: March 29, 2019							
Sampler: Amanda Peterson							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pioneer-63	Hallway, Outside Room C-231, Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-64	Hallway, Outside Room D-203/205, Hydration Station, Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-65	Hallway Outside Room D-203/205, Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-66	Room D-214, Kitchen Faucet	KF	3:08 PM	5	2	Y	First Draw
Pioneer-67	Hallway, Outside Room D-213, Hydration Station, Water Cooler	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-68	Hallway, Outside Room D-213, Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-69	Room D-231, Right Faucet	F	3:02 PM	5	5	Y	First Draw
Pioneer-71	Hallway, Outside Room C-310, Hydration Station, Bottle Fill	Not Sampled: Will be replaced with a Hydration Station or Filtered Water Cooler					
Pioneer-72	Hallway, Outside Room C-322, Hydration Station, Bottle Fill	BF	3:21 PM	5	ND	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb