



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE180861**

Pittsfield Elementary School							
Date of Sampling: 11/17/18							
Sampler: Jessica Perfetti							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pittsfield-06	Room 115, Bubbler	C	11:35 AM	5	6	N	First Draw. Corrosion on mouthpiece.
Pittsfield-36	Music Room, Faucet	C	12:04 PM	5	8	Y	First Draw. Corrosion on aerator.

Pittsfield Elementary School							
Date of Sampling: 12/22/18							
Sampler: Gary Bosh							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pittsfield-06A	Room 115, Bubbler	C	6:58 AM	5	2	N	Follow-Up First Draw Following Replacement
Pittsfield-36A	Music Room, Faucet	C	7:02 AM	5	6	Y	Follow-Up First Draw Following Replacement

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee

2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>

3) ND = Non Detected at Reported Detection Limit of 1 ug/L

4) NT = Not Tested



Ann Arbor Public Schools
 Lead Drinking Water Analysis
 Project Number: AE180861

Pittsfield Elementary School							
Date of Sampling: January 12, 2019							
Sampler: Jenna Sendra							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pittsfield-36B	Music Room, Faucet	C	2:04 PM	5	3	Y	2nd Follow-Up First Draw Following Replacement

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee

2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>

3) ND = Non Detected at Reported Detection Limit of 1 ug/L

4) NT = Not Tested