



Ann Arbor Public Schools
 Lead Drinking Water Analysis
 Project Number: AE180861

Pittsfield Elementary School							
Date of Sampling: November 17, 2018							
Sampler: Jessica Perfetti							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pittsfield-01	Hallway Across from Boiler Room, Bottle Fill, Water Cooler Outlet	BT	10:35 AM	5	ND ³	N	First Draw
Pittsfield-02	Staff Lounge, Kitchen Faucet	KF	11:20 AM	5	ND	Y	First Draw
Pittsfield-03	Hallway Across from Boiler Room, Bottle Fill Outlet	BT	10:36 AM	5	ND	N	First Draw
Pittsfield-04	Hallway Outside Room 106, Bubbler	C	11:00 AM	5	ND	N	First Draw
Pittsfield-05	Hallway Outside Gym, Bottle Fill Water Cooler Outlet	BT	11:59 AM	5	ND	N	First Draw.
Pittsfield-06	Room 115, Bubbler	C	11:35 AM	5		N	First Draw. Corrosion on mouthpiece.
Pittsfield-07	Room 101, Bubbler	C	10:39 AM	5	ND	N	First Draw
Pittsfield-08	Room 103, Bubbler	C	10:52 AM	5	ND	N	First Draw
Pittsfield-09	Room 106, Bubbler	C	11:03 AM	5	1	N	First Draw. Corrosion on mouthpiece.
Pittsfield-11	Room 108, Bubbler	C	10:48 AM	5	1	N	First Draw. Corrosion on mouthpiece.
Pittsfield-12	Room 109, Bubbler	C	11:16 AM	5	ND	N	First Draw
Pittsfield-13	Hallway Outside Gym, Bottle Fill Outlet	BT	12:00 PM	5	ND	Y	First Draw
Pittsfield-14	Room 115, Faucet	C	11:36 AM	5	2	Y	First Draw. Corrosion on aerator.
Pittsfield-15	Room 101, Faucet	C	10:40 AM	5	ND	Y	First Draw



Ann Arbor Public Schools
 Lead Drinking Water Analysis
 Project Number: AE180861

Pittsfield Elementary School							
Date of Sampling: November 17, 2018							
Sampler: Jessica Perfetti							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pittsfield-16	Room 103, Faucet	C	10:53 AM	5	3	N	First Draw
Pittsfield-17	Room 106, Faucet	C	11:04 AM	5	2	Y	First Draw
Pittsfield-18	Room 107, Faucet	C	Not Sampled.			Y	Hot & Cold are switched.
Pittsfield-19	Room 108, Faucet	C	10:49 AM	5	ND	Y	First Draw. Corrosion on aerator.
Pittsfield-20	Room 109, Faucet	C	11:17 AM	5	1	Y	First Draw
Pittsfield-21	Room 105, Bubbler	C	11:07 AM	5	ND	N	First Draw
Pittsfield-22	Room 105, Faucet	C	11:08 AM	5	1	Y	First Draw. Corrosion on aerator.
Pittsfield-23	Room 104, Bubbler	C	11:11 AM	5	ND	N	First Draw. Corrosion on mouthpiece.
Pittsfield-24	Room 104, Faucet	C	11:12 AM	5	2	Y	First Draw
Pittsfield-25	Room 102, Bubbler	C	Not Sampled.			N	Low Flow.
Pittsfield-26	Room 102, Faucet	C	10:45 AM	5	3	Y	First Draw. Corrosion on aerator.
Pittsfield-27	Room 116, Bubbler	C	Not Sampled.			N	Low Flow.
Pittsfield-28	Room 116, Faucet	C	11:29 AM	5	ND	Y	First Draw. Corrosion on aerator.
Pittsfield-29	Room 114, Bubbler	C	11:39 AM	5	ND	N	First Draw. Corrosion on mouthpiece.
Pittsfield-30	Room 114, Faucet	C	11:40 AM	5	1	Y	First Draw
Pittsfield-31	Room 112, Bubbler	C	11:47 AM	5	ND	N	First Draw. Corrosion on mouthpiece.
Pittsfield-32	Room 112, Faucet	C	11:48 AM	5	ND	Y	First Draw
Pittsfield-33	Room 111, Bubbler	C	11:51 AM	5	ND	N	First Draw. Corrosion on mouthpiece.
Pittsfield-34	Room 111, Faucet	C	11:52 AM	5	1	Y	First Draw. Corrosion on aerator.
Pittsfield-35	Music Room, Bubbler	C	12:03 PM	5	3	N	First Draw. Sampled bottom of bubbler.



Ann Arbor Public Schools
 Lead Drinking Water Analysis
 Project Number: AE180861

Pittsfield Elementary School

Date of Sampling: November 17, 2018

Sampler: Jessica Perfetti

Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pittsfield-36	Music Room, Faucet	C	12:04 PM	5		Y	First Draw. Corrosion on aerator.
Pittsfield-37	Kitchen, 3-Compartment Sink, Faucet	KF	12:10 PM	5	ND	N	First Draw
Pittsfield-39	Media Center, Faucet	F	11:44 AM	5	1	Y	First Draw. Corrosion on aerator.

Date of Sampling: January 12, 2019

Sampler: Jenna Sendra

Pittsfield-18	Room 107, Faucet	C	2:07 PM	5	2	Y	IFD
Pittsfield-25	Room 102, Bubbler	C	2:08 PM	5	ND	N	IFD
Pittsfield-27	Room 116, Bubbler	C	2:02 PM	5	ND	N	IFD