



Ann Arbor Public Schools  
 Lead Drinking Water Analysis  
 Project Number: AE180861

Ann Arbor STEAM at Northside

Date of Sampling: 11/3/2018

Sampler: Steven Ripley

Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Steam -01	Room 101, Bubbler	C	3:33 PM	5	1	N	First Draw. Rust.
Steam -02	Room 104, Bubbler	C	3:38 PM	5	1	N	First Draw. Rust.
Steam -03	Staff Lounge, Faucet	KF	1:15 PM	5	3	Y	First Draw
Steam -04	Room 503, Bubbler	C	4:05 PM	5	2	N	First Draw. Staining on Mouthpiece.
Steam -05	Room 401, Bubbler	C	4:14 PM	5	1	N	First Draw. Staining on Mouthpiece.
Steam -06	Room 501, Bubbler	C	4:10 PM	5	2	N	First Draw. Staining, Leaks at Base.
Steam -07	Gym, Left Bubbler	B	2:10 PM	5	1	N	First Draw
Steam -08	Hallway, Outside Gym Left Bubbler	B	2:08 PM	5	ND <sup>3</sup>	N	First Draw
Steam -09	Hallway, Outside Kitchen, Hydration Station Water Cooler	BT	2:15 PM	5	1	N	First Draw
Steam -10	Room MS-3, In Closet, Faucet	F	3:54 PM	5	6	Y	First Draw
Steam -11	Room MS-2, In Closet, Faucet	F	3:55 PM	5	3	Y	First Draw
Steam -12	Hallway, Outside MS-1, Left Bubbler	B	3:48 PM	5	3	Y	First Draw. Rust.
Steam -13	Room K-3, Bubbler	C	3:42 PM	5	ND	N	First Draw
Steam -14	Room K-3, Faucet	C	3:42 PM	5	1	Y	First Draw. Corrosion on Aerator.
Steam -15	Room 104, Faucet	C	3:38 PM	5	ND	Y	First Draw
Steam -16	Room 103, Bubbler	C	3:40 PM	5	2	N	First Draw. Rust.
Steam -17	Room 103, Faucet	C	3:40 PM	5	2	Y	First Draw. Corrosion on Aerator.
Steam -18	Room 102, Bubbler	C	3:34 PM	5	2	N	First Draw. Rust.
Steam -19	Room 102, Faucet	C	3:35 PM	5	4	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools  
 Lead Drinking Water Analysis  
 Project Number: AE180861

Ann Arbor STEAM at Northside							
Date of Sampling: 11/3/2018							
Sampler: Steven Ripley							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Steam -20	Room 101, Faucet	C	3:33 PM	5	2	Y	First Draw. Corrosion on Aerator.
Steam -21	Room K-2, Bubbler	B	3:31 PM	5	4	N	First Draw
Steam -22	Room K-2, Faucet	C	3:32 PM	5	3	Y	First Draw. Corrosion on Aerator.
Steam -23	Room K-1, Bubbler	C	3:28 PM	5	4	N	First Draw
Steam -24	Room K-1, Faucet	C	3:29 PM	5	4	Y	First Draw. Corrosion on Aerator.
Steam -25	Room MS-5, In Closet, Faucet	F	Not Sampled				Irregular Flow, brown color. Unused faucet. Did Not Sample.
Steam -26	Room MS-1, In Closet, Faucet	F	3:50 PM	5	45	Y	First Draw
Steam -27	Nurse's Clinic Faucet	F	1:14 PM	5	5	Y	First Draw
Steam -28	Hallway, Outside Teachers Lounge, Right Bubbler	B	1:18 PM	5	2	N	First Draw. Rust.
Steam -29	Hallway, Outside Teachers Lounge, Left Bubbler	B	1:18 PM	5	2	N	First Draw. Rust.
Steam -30	Room 503, Faucet	C	4:07 PM	5	4	Y	First Draw. Corrosion on Aerator.
Steam -31	Room 502, Bubbler	C	4:08 PM	5	3	N	First Draw
Steam -32	Room 502, Faucet	C	4:09 PM	5	3	Y	First Draw
Steam -33	Room 501, Faucet	C	4:11 PM	5	3	Y	First Draw. Corrosion on aerator. Low Flow.
Steam -34	Room 403, Bubbler	C	4:12 PM	5	2	N	First Draw. Staining on Mouthpiece.
Steam -35	Room 403, Faucet	C	4:13 PM	5	3	Y	First Draw. Corrosion on Aerator.
Steam -36	Room 401, Faucet	C	4:14 PM	5	5	Y	First Draw. Corrosion on Aerator.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools  
 Lead Drinking Water Analysis  
 Project Number: AE180861

Ann Arbor STEAM at Northside							
Date of Sampling: 11/3/2018							
Sampler: Steven Ripley							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Steam -37	Room 402, Bubbler	C	4:15 PM	5	2	N	First Draw. Staining on Mouthpiece.
Steam -38	Room 402, Faucet	C	4:16 PM	5	3	Y	First Draw. Corrosion on Aerator.
Steam - 39	Hallway, Outside Gym Right Bubbler	B	2:07 PM	5	2	N	First Draw
Steam -40	Gym, Right Bubbler	B	2:10 PM	5	2	N	First Draw
Steam -41	Media Center, Faucet	F	Not Sampled				Room Not Accessible. Did Not Sample.
Steam -42	Hallway, Outside Kitchen, Hydration Station Bottle Fill	BT	2:15 PM	5	ND	Y	First Draw
Steam -43	Kitchen 3-Compartment Sink, Single Faucet	KS	4:21 PM	5	ND	Y	First Draw
Steam -44	Multi-Purpose Room, Water Cooler	WC	2:18 PM	5	ND	N	First Draw
Steam -45	Room 303, Faucet	C	4:26 PM	5	31	Y	First Draw. Corrosion on Aerator.
Steam -46	Room 303, Bubbler	C	4:26 PM	5	1	N	First Draw
Steam -47	Room 302, Faucet	C	4:27 PM	5	4	Y	First Draw. Corrosion on Aerator.
Steam -48	Room 303, Bubbler	C	4:27 PM	5	2	N	First Draw. Staining on Mouthpiece.
Steam -49	Room 301, Faucet	C	4:28 PM	5	4	Y	First Draw. Corrosion on Aerator.
Steam -50	Room 301, Bubbler	C	4:29 PM	5	ND	N	First Draw. Staining on Mouthpiece.
Steam -51	Room 203, Faucet	C	4:30 PM	5	11	Y	First Draw. Corrosion on Aerator.
Steam -52	Room 203, Bubbler	C	4:31 PM	5	ND	N	First Draw. Iron.
Steam -53	Room 202, Faucet	C	4:32 PM	5	6	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools  
 Lead Drinking Water Analysis  
 Project Number: AE180861

Ann Arbor STEAM at Northside							
Date of Sampling: 11/3/2018							
Sampler: Steven Ripley							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Steam -54	Room 202, Bubbler	C	4:32 PM	5	4	N	First Draw. Staining on Mouthpiece.
Steam -55	Room 201, Faucet	C	4:33 PM	5	ND	Y	First Draw. Corrosion on Aerator.
Steam -56	Room 201, Bubbler	C	4:33 PM	5	ND	N	First Draw. Staining on Mouthpiece.
Steam -57	Hallway, Outside MS-6, Hydration Station Bottle Fill	BT	3:58 PM	5	ND	Y	First Draw
Steam -58	Hallway, Outside MS-6, Hydration Station Water Cooler	BT	3:58 PM	5	ND	N	First Draw
Steam -59	Hallway, Outside MS-1, Right Bubbler	B	3:48 PM	5	ND	N	First Draw. Rust.

Ann Arbor STEAM at Northside							
Date of Sampling: 11/3/2018							
Sampler: Steven Ripley							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Steam -25	Room MS-5, In Closet, Faucet	C	3:33 PM	5	4	N	First Draw. Rust.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminant>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested

Action Level >5ppb