



Ann Arbor Public Schools  
 Lead Drinking Water Analysis  
 Project Number: AE180861

Tappan Middle School							
Date of Sampling: 01/21/2019							
Sampler: Alec Staber							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-01	Hallway Outside Room 122, Water Cooler	WC	Not Sampled.				Scheduled for replacement with a hydration station.
Tappan-02	Room 102, Faucet	F	12:53 PM	5	ND <sup>3</sup>		First Draw
Tappan-03	Hallway Outside Room 138, Bubbler	B	Not Sampled.				Scheduled for replacement with a hydration station.
Tappan-04	Cafeteria, Hydration Station Water Cooler	WC	12:28 PM	5	1		First Draw
Tappan-05	Hallway Outside Room 240, Hydration Station Bottle Fil	WC	1:04 PM	5	ND		First Draw
Tappan-06	Hallway Outside Room 220, Water Cooler	WC	Not Sampled.				Scheduled for replacement with a hydration station.
Tappan-07	Hallway Adjacent to Room 208, Across Stairwell, Water Cooler	WC	Not Sampled.				Scheduled for replacement with a hydration station.
Tappan-08	Room 202, Faucet	F	1:19 PM	5	ND	Y	First Draw
Tappan-09	Hallway Outside Room 288, Water Cooler	WC	Not Sampled.				Scheduled for replacement with a hydration station.
Tappan-10	Room 304, Faucet	F	1:55 PM	5	ND	Y	First Draw
Tappan-11	Hallway Adjacent to Room 308, Across Stairwell, Hydration Station Water Cooler	BT	1:50 PM	5	ND		First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools  
Lead Drinking Water Analysis  
Project Number: AE180861

Tappan Middle School							
Date of Sampling: 01/21/2019							
Sampler: Alec Staber							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-12	Hallway Outside Room 320, Bubblers	B	Not Sampled.				Scheduled for replacement with a hydration station.
Tappan-13	Nurse's Clinic, Faucet	F	12:20 PM	5	3	Y	First Draw
Tappan-14	Cafeteria, Hydration Station Bottle Fill	BT	12:28 PM	5	2		First Draw
Tappan-15	OPEN NUMBER						
Tappan-16	Kitchen, 2-Compartment Sink, Right Faucet	KF	12:25 PM	5	2	N	First Draw
Tappan-17	Room 374, Sink Pair Closest to Entry Door, Left Sink Faucet	F	1:44 PM	5	3	Y	First Draw
Tappan-18	Pool, Bubblers on West Wall & Girls Locker Room	B	12:38 PM	5	4		First Draw
Tappan-19	Pool, Bubblers on East Wall & Boys Locker Room	B	12:40 PM	5	4		First Draw
Tappan-20	Girl's Locker Room, Bubblers	B	12:32 PM	5	2		First Draw
Tappan-21	Boy's Locker Room, Bubblers	B	12:35 PM	5	ND		First Draw
Tappan-22	Multi-Purpose Room, Bubblers	B	12:45 PM	5	ND		First Draw
Tappan-23	Room 191, Bubblers	B	Not Sampled.				Out of Service.

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminant>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested



Ann Arbor Public Schools  
Lead Drinking Water Analysis  
Project Number: AE180861

Tappan Middle School							
Date of Sampling: 01/21/2019							
Sampler: Alec Staber							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-24	Room 192, Bubbler	B	Not Sampled.				Out of Service.
Tappan-25	Hallway, Adjacent to Boiler Room Across Stairwell, Bubbler	B	Not Sampled.				Scheduled for replacement with a hydration station.
Tappan-26	Room 106, Faucet	F	12:50 PM	5	1	Y	First Draw
Tappan-27	Room 104, Faucet	F	12:52 PM	5	ND	Y	First Draw
Tappan-28	Second Floor Teacher's Lounge, Kitchen Faucet	F	1:24 PM	5	5	Y	First Draw
Tappan-29	Room 256, Faucet	F	1:04 PM	5	4	N	First Draw
Tappan-30	Media Center, Kitchen Faucet	KF	1:00 PM	5	6	Y	First Draw
Tappan-31	Gym, South Wall, Right Bubbler	B	1:14 PM	5	ND		First Draw
Tappan-32	Gym, South Wall, Left Bubbler	B	1:15 PM	5	ND		First Draw
Tappan-33	Room 204, Faucet	F	1:20 PM	5	ND	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminant>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested



Ann Arbor Public Schools  
 Lead Drinking Water Analysis  
 Project Number: AE180861

Tappan Middle School							
Date of Sampling: 01/21/2019							
Sampler: Alec Staber							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-34	Room 302, Faucet	F	1:05 PM	5	3	Y	First Draw. Corrosion around Aerator.
Tappan-35	Hallway Adjacent to Room 308, Across Stairwell, Hydration Station Bottle Fill	BT	1:50 PM	5	ND		First Draw
Tappan-36	OPEN NUMBER						
Tappan-37	Third Floor Teacher's Lounge, Kitchen Faucet	C	1:29 PM	5	7	Y	Rust and Corrosion. First Draw.
Tappan-38	Hallway, Outside Room 337, Water Cooler	WC	Not Sampled.				Scheduled for replacement with a hydration station.
Tappan-39	Room 363, Single Sink, Farthest from Entry Door at Exterior Wall	F	1:34 PM	5	21	Y	First Draw
Tappan-40	Room 363, Middle Sink Pair, Right Sink Faucet	F	1:35 PM	5	3	Y	First Draw
Tappan-41	Room 363, Middle Sink Pair, Left Sink Faucet	F	1:36 PM	5	11	y	First Draw
Tappan-42	Room 363, Sink Pair Closest to Entry Door, Right Sink Faucet	F	1:36 PM	5	9	Y	First Draw
Tappan-43	Room 363, Sink Pair Closest to Entry Door, Left Sink Faucet	F	1:37 PM	5	5	Y	First Draw
Tappan-44	Room 374, Single Sink, Farthest from Entry Door at Exterior Wall	F	1:46 PM	5	40	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminant>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools  
 Lead Drinking Water Analysis  
 Project Number: AE180861

Tappan Middle School							
Date of Sampling: 01/21/2019							
Sampler: Alec Staber							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-45	Room 374, Middle Sink Pair, Right Sink Faucet	F	Not Sampled.				Out of Service.
Tappan-46	Room 374, Middle Sink Pair, Left Sink Faucet	F	1:46 PM	5	9	Y	First Draw
Tappan-47	Room 374, Sink Pair Closest to Entry Door, Right Sink Faucet	F	1:45 PM	5	5	Y	Corrosion. First Draw.
Tappan-48	Hallway Outside Room 240, Hydration Station Water Cooler	BT	1:05 PM	5	ND		First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested

Action Level >5ppb