



Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Wines ES-01	Room 112, Bubblers	C	11:39 AM	5	ND ³	N	First Draw
Wines ES-02	Room 114, Bubblers	C	11:42 AM	5	4	N	First Draw
Wines ES-03	Room 116, Bubblers	C	11:44 AM	5	ND	N	First Draw
Wines ES-04	Room 115, Bubblers	C	11:46 AM	5	7	N	First Draw
Wines ES-05	Room 117, Bubblers	C	N/A	5	N/A	N	Low Flow, Did Not Sample
Wines ES-06	Room 118, Bubblers	C	11:48 AM	5	ND	N	First Draw
Wines ES-07	Room 119, Bubblers	C	11:51 AM	5	ND	N	First Draw
Wines ES-08	Room 120, Bubblers	C	11:57 AM	5	ND	N	First Draw
Wines ES-09	Hallway, Across from Kitchen, Bottle Fill, Water Cooler	BT	11:27 AM	5	ND	N	First Draw
Wines ES-10	Teachers Lounge, Faucet	C	11:35 AM	5	7	Y	First Draw
Wines ES-11	Kitchen, Single Compartment Faucet	KS	11:32 AM	5	4	Y	First Draw
Wines ES-12	Kitchen, 3-Compartment Faucet	KS	11:33 AM	5	ND	Y	First Draw
Wines ES-13	Room 112, Faucet	C	11:40 AM	5	ND	Y	First Draw
Wines ES-14	Room 114, Faucet	C	11:43 AM	5	3	Y	First Draw
Wines ES-15	Room 115, Faucet	C	11:46 AM	5	6	Y	First Draw
Wines ES-16	Room 116, Faucet	C	11:45 AM	5	ND	Y	First Draw
Wines ES-17	Room 117, Faucet	C	11:50 AM	5	1	Y	First Draw, Slow Drain
Wines ES-18	Room 118, Faucet	C	11:49 AM	5	ND	Y	First Draw
Wines ES-19	Room 119, Faucet	C	11:52 AM	5	ND	Y	First Draw
Wines ES-20	Room 120, Faucet	C	11:54 AM	5	ND	Y	First Draw

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Wines ES-21	Hallway, Across from Kitchen, Bottle Fill	BT	11:28 AM	5	ND	N	First Draw
Wines ES-22	Gym, Bubbler	B	N/A	5	N/A	N	Out of Service, Did Not Sample
Wines ES-23	Portable, Hallway, Right Water Cooler	WC	11:17 AM	5	11	N	First Draw, , Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.
Wines ES-24	Athletic Storage, Bubbler	B	11:27 AM	5	21	N	First Draw
Wines ES-25	Teachers Lounge, Bubbler	C	11:24 AM	5	1	N	First Draw
Wines ES-26	Student Workroom Access Gym	F	11:29 AM	5	1	Y	First Draw
Wines ES-27	Media Center, Faucet	KS	11:30 AM	5	ND	N	First Draw
Wines ES-28	Main Office, Nurses, Faucet	F	11:26 AM	5	ND	Y	First Draw, Corrosion
Wines ES-29	Room 113, Bubbler	C	11:56 AM	5	ND	N	First Draw, Corrosion, Slow Drain
Wines ES-30	Room 113, Faucet	C	11:57 AM	5	5	Y	First Draw, Corrosion, Slow Drain, Leaky
Wines ES-31	Room 111, Bubbler	C	11:58 AM	5	5	N	First Draw, Corrosion
Wines ES-32	Room 111, Faucet	C	11:59 AM	5	11	Y	First Draw, Corrosion
Wines ES-33	Room 110, Bubbler	C	12:00 PM	5	7	N	First Draw
Wines ES-34	Room 110, Faucet	C	12:01 PM	5	68	Y	First Draw
Wines ES-35	Room 108, Bubbler	C	12:04 PM	5	5	N	First Draw
Wines ES-36	Room 108, Faucet	C	12:05 PM	5	4	Y	First Draw
Wines ES-37	Room 109, Bubbler	C	12:02 PM	5	1	N	First Draw, Corrosion
Wines ES-38	Room 109, Faucet	C	12:03 PM	5	2	Y	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Wines ES-39	Room 107, Bubblers	C	12:08 PM	5	2	N	First Draw
Wines ES-40	Room 107, Faucet	C	12:09 PM	5	ND	Y	First Draw, Corrosion
Wines ES-41	Room 106, Bubblers	C	12:06 PM	5	4	N	First Draw
Wines ES-42	Room 106, Faucet	C	12:07 PM	5	5	Y	First Draw
Wines ES-43	Room 104, Bubblers	C	12:12 PM	5	2	N	First Draw, Dirty Sink
Wines ES-44	Room 104, Faucet	C	12:13 PM	5	ND	Y	First Draw, Dirty Sink
Wines ES-45	Room 105, Bubblers	C	12:10 PM	5	2	N	First Draw
Wines ES-46	Room 105, Faucet	C	12:11 PM	5	ND	Y	First Draw
Wines ES-47	Room 103, Bubblers	C	12:16 PM	5	2	N	First Draw, Corrosion, Slow Drain
Wines ES-48	Room 103, Faucet	C	12:17 PM	5	2	Y	First Draw, Corrosion, Slow Drain
Wines ES-49	Room 102, Bubblers	C	12:14 PM	5	ND	N	First Draw, Slow Drain
Wines ES-50	Room 102, Faucet	C	12:15 PM	5	ND	Y	First Draw, Slow Drain
Wines ES-51	Room 100, Right Bubblers	C	12:24 PM	5	1	N	First Draw, Corrosion, Slow Drain
Wines ES-52	Room 100, Right Faucet	C	12:25 PM	5	3	Y	First Draw, Corrosion, Slow Drain
Wines ES-53	Room 100, Left Bubblers	C	12:25 PM	5	2	N	First Draw, Corrosion
Wines ES-54	Room 100, Left Faucet	C	12:26 PM	5	1	Y	First Draw
Wines ES-55	Room 101, Right Bubblers	C	12:20 PM	5	ND	N	First Draw
Wines ES-56	Room 101, Right Faucet	C	12:21 PM	5	ND	Y	First Draw, Corrosion
Wines ES-57	Room 101, Left Bubblers	C	12:22 PM	5	ND	N	First Draw
Wines ES-58	Room 101, Left Faucet	C	12:33 PM	5	1	Y	First Draw, Corrosion

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Wines ES-59	Portable, Hallway, Left Water Cooler	WC	11:18 AM	5	ND	N	First Draw, Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested