



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE190030**

Tappan Middle School							
Date of Sampling: 2/22/2020							
Sampler: Alex Reiber							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-01	Hallway, Outside Room 122, Hydration Station, Water Cooler	BT	8:10 AM	5	ND ³	N	First Draw, Filtered.
Tappan-02	Room 102, Faucet	F	1:00 PM	5	ND	Y	First Draw, Filtered.
Tappan-03	Hallway, Outside Room 138, Hydration Station, Water Cooler	BT	8:05 AM	5	2	N	First Draw, Filtered.
Tappan-04	Cafeteria, Hydration Station, Water Cooler	BT	8:35 AM	5	3	N	First Draw, Filtered.
Tappan-05	Hallway, Outside Room 240, Hydration Station, Bottle Fill	BT	8:00 AM	5	3	N	First Draw, Filtered.
Tappan-06	Hallway, Outside Room 220, Hydration Station, Water Cooler	BT	8:00 AM	5	ND	N	First Draw, Filtered.
Tappan-07	Hallway, Adjacent to Room 208, Across Stairwell, Hydration Station, Water Cooler	BT	7:55 AM	5	ND	N	First Draw, Filtered.
Tappan-08	Room 202, Faucet	F	10:15 AM	5	ND	Y	First Draw, Filtered.
Tappan-09	Hallway, Outside Room 288, Single Water Cooler	WC	7:55 AM	5	ND	N	First Draw, Filtered.
Tappan-10	Room 304, Faucet	F	8:55 AM	5	ND	Y	First Draw, Filtered.
Tappan-11	Hallway, Adjacent to Room 308, Across Stairwell, Hydration Station, Water Cooler	BT	8:50 AM	5	ND	N	First Draw, Filtered.
Tappan-12	Hallway, Outside Room 320, Hydration Station, Water Cooler	BT	8:50 AM	5	ND	N	First Draw, Filtered.
Tappan-13	Nurse's Clinic, Faucet	F	10:45 AM	5	ND	Y	First Draw, Filtered.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumbed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE190030**

Tappan Middle School							
Date of Sampling: 2/22/2020							
Sampler: Alex Reiber							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-14	Cafeteria, Hydration Station, Bottle Fill	BT	8:35 AM	5	ND	N	First Draw, Filtered.
Tappan-15	Hallway, Outside Room 122, Hydration Station, Bottle Fill	BT	8:10 AM	5	ND	N	First Draw, Filtered.
Tappan-16	Kitchen, 2-Compartment Sink, Add On Single Faucet, Far Right	KF	12:45 PM	5	ND	Y	First Draw, Filtered.
Tappan-17	Room 374, Sink Pair Closest to Entry Door, Left Sink Faucet	F	9:20 AM	5	3	Y	First Draw, Filtered.
Tappan-18	Pool, Bubbler on West Wall & Girls Locker Room	B	8:25 AM	5	ND	N	First Draw, Filtered.
Tappan-19	Pool, Bubbler on East Wall & Boys Locker Room	B	8:25 AM	5	ND	N	First Draw, Filtered.
Tappan-20	Girl's Locker Room, Bubbler	B	8:35 AM	5	ND	N	First Draw, Filtered.
Tappan-21	Boy's Locker Room, Bubbler	B	8:25 AM	5	ND	N	First Draw, Filtered.
Tappan-22	Multi-Purpose Room, Bubbler	B	8:15 AM	5	ND	N	First Draw, Filtered.
Tappan-23	Room 191, Single Water Cooler	WC	8:20 AM	5	ND	N	First Draw, Filtered.
Tappan-24	Room 192, Single Water Cooler	WC	10:45 AM	5	ND	N	First Draw, Filtered.
Tappan-25	Hallway, Adjacent to Boiler Room, Across Stairwell, Hydration Station, Water Cooler	BT	8:10 AM	5	ND	N	First Draw, Filtered.
Tappan-26	Room 106, Faucet	F	12:50 PM	5	ND	Y	First Draw, Filtered.
Tappan-27	Room 104, Faucet	F	12:55 PM	5	ND	Y	First Draw, Filtered.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE190030**

Tappan Middle School							
Date of Sampling: 2/22/2020							
Sampler: Alex Reiber							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-28	Second Floor, Teacher's Lounge, Combination Sink, Faucet	C	10:10 AM	5	2	N	First Draw, Filtered.
Tappan-29	Room 256, Faucet	F	9:55 AM	5	ND	N	First Draw, Filtered.
Tappan-30	Media Center, Kitchen Faucet	KF	1:05 PM	5	2	Y	First Draw, Filtered.
Tappan-31	Gymnasium, South Wall, Right Combination Drinking Fountain/Glass Filler, Bubbler Outlet	BT	7:45 AM	5	ND	N	First Draw, Filtered.
Tappan-32	Gymnasium, South Wall, Left Combination Drinking Fountain/Glass Filler, Bubbler Outlet	BT	7:45 AM	5	ND	N	First Draw, Filtered.
Tappan-33	Room 204, Faucet	F	10:15 AM	5	ND	Y	First Draw, Filtered.
Tappan-34	Room 302, Faucet	F	9:00 AM	5	ND	Y	First Draw, Filtered.
Tappan-35	Hallway, Adjacent to Room 308, Across Stairwell, Hydration Station, Bottle Fill	BT	8:50 AM	5	ND	N	First Draw, Filtered.
Tappan-36	Third Floor, Teacher's Lounge, Combination Sink, Bubbler	C	9:10 AM	5	13	N	First Draw, Filtered.
Tappan-37	Third Floor, Teacher's Lounge, Combination Sink, Faucet	C	9:10 AM	5	ND	Y	First Draw, Filtered.
Tappan-38	Hallway, Outside Room 337, Hydration Station, Water Cooler	BT	8:45 AM	5	ND	N	First Draw, Filtered.
Tappan-39	Room 363, Single Sink, Farthest from Entry Door at Exterior Wall	F	10:25 AM	5	3	Y	First Draw, Filtered.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumbed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE190030**

Tappan Middle School							
Date of Sampling: 2/22/2020							
Sampler: Alex Reiber							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-40	Room 363, Middle Sink Pair, Right Sink, Faucet	F	10:25 AM	5	8	Y	First Draw, Filtered.
Tappan-41	Room 363, Middle Sink Pair, Left Sink, Faucet	F	10:25 AM	5	2	Y	First Draw, Filtered.
Tappan-42	Room 363, Sink Pair Closest to Entry Door, Right Sink, Faucet	F	10:25 AM	5	ND	Y	First Draw, Filtered.
Tappan-43	Room 363, Sink Pair Closest to Entry Door, Left Sink, Faucet	F	10:25 AM	5	11	Y	First Draw, Filtered.
Tappan-44	Room 374, Single Sink, Farthest from Entry Door at Exterior Wall	F	9:20 AM	5	97	Y	First Draw, Filtered.
Tappan-45	Room 374, Middle Sink Pair, Right Sink, Faucet	F	9:20 AM	5	41	Y	First Draw, Filtered.
Tappan-46	Room 374, Middle Sink Pair, Left Sink, Faucet	F	9:20 AM	5	3	Y	First Draw, Filtered.
Tappan-47	Room 374, Sink Pair Closest to Entry Door, Right Sink, Faucet	F	9:20 AM	5	2	Y	First Draw, Filtered.
Tappan-48	Hallway, Outside Room 240, Hydration Station, Water Cooler	BT	8:00 AM	5	ND	N	First Draw, Filtered.
Tappan-49	Hallway, Outside Room 138, Hydration Station, Bottle Fill	BT	8:05 AM	5	ND	N	First Draw, Filtered.
Tappan-50	Hallway, Outside Room 220, Hydration Station, Bottle Fill	BT	8:00 AM	5	ND	N	First Draw, Filtered.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumbed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE190030**

Tappan Middle School							
Date of Sampling: 2/22/2020							
Sampler: Alex Reiber							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-51	Hallway, Adjacent to Room 208, Across Stairwell, Hydration Station, Bottle Fill	BT	7:55 AM	5	ND	N	First Draw, Filtered.
Tappan-52	Hallway, Outside Room 320, Hydration Station, Water Cooler	BT	8:50 AM	5	ND	N	First Draw, Filtered.
Tappan-53	Hallway, Adjacent to Boiler Room Across Stairwell, Hydration Station, Bottle Fill	BT	8:10 AM	5	ND	N	First Draw, Filtered.
Tappan-54	Hallway, Outside Room 337, Hydration Station, Bottle Fill	BT	8:45 AM	5	ND	N	First Draw, Filtered.
Tappan-55	Second Floor, Teacher's Lounge, Combination Sink, Bubbler	C	10:10 AM	5	6	N	First Draw, Filtered.
Tappan-56	Gymnasium, South Wall, Right Combination Drinking Fountain/Glass Filler, Glass Fill Outlet	BT	7:45 AM	5	ND	N	First Draw, Filtered.
Tappan-57	Gymnasium, South Wall, Left Combination Drinking Fountain/Glass Filler, Glass Fill Outlet	BT	7:45 AM	5	ND	N	First Draw, Filtered.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumbed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE190030**

Tappan Middle School							
Date of Sampling: 2/29/2020							
Sampler: Carly Doulos							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-36A	Third Floor, Teacher's Lounge, Combination Sink, Bubblers	C	12:51 PM	5	8	N	Follow-up Flush, Filtered.
Tappan-40A	Room 373, Middle Sink Pair, Right Sink, Faucet	F	12:59 PM	5	7	Y	Repeat First Draw, Filtered.
Tappan-43A	Room 373, Sink Pair Closest to Entry Door, Left Sink, Faucet	F	12:56 PM	5	8	Y	Repeat First Draw, Filtered.
Tappan-44A	Room 374, Single Sink, Farthest from Entry Door at Exterior Wall	F	1:09 PM	5	ND ³	Y	Follow-up Flush, Filtered.
Tappan-45A	Room 374, Middle Sink Pair, Right Sink, Faucet	F	1:05 PM	5	ND	Y	Follow-up Flush, Filtered.
Tappan-55A	Second Floors Teacher's Lounge, Combination Sink, Bubblers	C	12:46 PM	5	5	N	Follow-up Flush, Filtered.

Tappan Middle School							
Date of Sampling: N/A							
Sampler: N/A							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-36	Third Floor, Teacher's Lounge, Combination Sink, Bubblers	C	N/A	5	N/A	N	Location Permanently Removed due to Infrequent Use.

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested

Action Level >5ppb



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE190030**

Tappan Middle School							
Date of Sampling: N/A							
Sampler: N/A							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Tappan-40	Room 373, Middle Sink Pair, Right Sink, Faucet	F	N/A	5	N/A	Y	Location Determined to be Nonpotable due to Lack of Use.
Tappan-43	Room 373, Sink Pair Closest to Entry Door, Left Sink, Faucet	F	N/A	5	N/A	Y	Location Determined to be Nonpotable due to Lack of Use.
Tappan-44	Room 374, Single Sink, Farthest from Entry Door at Exterior Wall	F	N/A	5	N/A	Y	Location Determined to be Nonpotable due to Lack of Use.
Tappan-45	Room 374, Middle Sink Pair, Right Sink, Faucet	F	N/A	5	N/A	Y	Location Determined to be Nonpotable due to Lack of Use.
Tappan-55	Second Floors Teacher's Lounge, Combination Sink, Bubbler	C	N/A	5	N/A	N	Location Permanently Removed due to Infrequent Use.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumbed Coffee
 2) <https://www.epa.gov/you-drinking-water/table-regulated-drinking-water-contaminants>
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L
 4) NT = Not Tested